

TOWNSHIP 28 RANGE 04 POINT IDENTIFIER # 400140

PRIMARY CORNER DESCRIPTION 1/4 Corner to Sections 33 & 34

Alias	Description

Original - W.H. Byars, under contract # 376 dated Jan. 22, 1881 (DCSO rec. Vol. 13, Pg. 5626)

Set Fir post for 1/4 Sec. Cor. from which:
 A Maple, 24" dia. bears East 45 lks. dist.
 A Maple, 24" dia. bears N.58°W., 83 lks. dist.

G.G. Stewart, Deputy County Surveyor - witnesses C.Crocker & Frank Evans, Jan. 30, 1922 M 2-4

Set - 1" iron pipe for corner at location in fence corner pointed out by Albert Robinson, who saw corner set in 1881. All BTs gone. Marked the following trees:
New BTs - A Fir, 24" dia. bears N.64°W., 226.0'
 A Maple, 12" dia. bears N.6°30'W., 101.0'
 (no other BT suitable)

James W. Byron, Deputy County Surveyor - April-May 1957. C.S. File No. 47/180.

Retrace Stewarts 1922 survey to fix position of this corner. (See file).
Set an iron pipe with brass cap at corner point mkd. ¼ S33/34 T28S, R4W, County Surveyor's Office, 1957.
New BTs - 14" Maple, S32°E., 100.0' mkd. ¼ S34 CS BT.
 10" Ewe wood fence post, S.40°W., 11.5' mkd. ¼ S33 CS BT.

Found OK, Sept. 1985 - B. Holt M 99-40.
Found OK by G. Lang, August 1999 - M133-18 A & B
FD. Ok by G. Lang, 10/2006 - 2007-0008
Fd. BC by D Edwards - 6/2022 - 2022-0030