

TOWNSHIP 28 RANGE 04 POINT IDENTIFIER # 440140

PRIMARY CORNER DESCRIPTION Center 1/4 Section 34.

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas Co. Surveyors Office - G.G. Stewart, Deputy Co. Surveyor - For: Dr. Banks Feb.27, 1922. M 2-4 & Vol 3, Pg. 113.

-----  
Set - Iron Pipe.  
BTs - 24" Fir, bears N.15°W., 9.0'.  
18" Fir, bears S.57½°E., 34.0'.

**THIS CORNER IS NOT ACCEPTED BY B. HOLT SEE 9/1985**  
**SURVEY M 99-40 & C.S. File 58/298-3 (NAR)**

Burt Holt - For: Sun Studs Inc. - 9/85 - M 99-40 & C.S. 58/298-3 (Narrative). (Information added 1/18/2001)

-----  
Found - 1" IP set by G.G. Stewart, Deputy County Surveyor, in 1922, Per M 2-4  
32" Fir, bears N.15°W., 9.0 ft. scribing visible.  
28" Fir stump, bears S.57½°E., 34.0 ft. scribing visible.

NOTE - This position is not accepted.  
(Excerpt from narrative) An error was found in the traverse distance between Stewart's C ¼ corner & the East ¼ of sec. 34. Then traversed through all four quarter corners. This traverse indicated that Stewart's corner was out of position by 33.44 ft. **(TRUE POSITION BEARS S.9°50'59"E., 33.44 FT FROM STEWART'S I.P.)**

This corner has been used as a property corner for over 50 years, so I did not set a corner at the correct position.

Found Stewart's IP & BTs, N.9°50'59"W., 33.44 FT from calc. C¼ corner. G. Lang, August 1999 - M133-18 A&B