

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by George S. Pershin, under Contract #238, Dated, July 13, 1875 - (DCSO records Vol. 14 Page(s) 5829)

Set Fir post for ¼ sec. cor. on top of bluff, from which
A Hemlock 16" dia., bears N.45°E., 30 lks. dist.
A Chestnut 8" dia., bears S.43°W., 78 lks. dist.

G. Robert Lecklider -Wit: Dale McFarland - Jan. 1961 - C.S. File 51/162

Found ½" Galv. Iron pipe on West R/W of Reston Co. Rd. and 2 old "X's" which I counted the rings to determine the age of said X's, to be 24 years (or about 1936). I accepted this as the location of the original corner because it fit the call on top of the ridge as per original field notes and on the strength of a penciled notation in Vol. 14 Pg. 5829, GLO field notes and I quote: " 16" Hemlock N.35°E. 30 lks. This is only tree standing and it is in decay. August 1936. CCC truck trail locator reports: A truck trail might destroy this tree but he will put in a pipe at the corner if it does and will mark some other trees. A Chestnut 8" S.43°W. 78 lks." End of quote.

I found very old blazes running West from this pipe. The timber to the East is small 2nd growth now and no blazes could be found. From this pipe, a point N.35°E., 30 lks. (the location of the BT. at that time would fall in the existing road.)

Set steel tube with survey cap alongside pipe in mound of stone. Scribed:

16" Fir N.30°E., 17.4 ft.

16" Fir S.21°E., 6.7 ft.

Corner falls 24 ft. West of the center of Reston Ridge Co. Rd

Douglas Co. Surveyors Office - John M. Powell, and crew - April 15, 1970 - C.S. File 54/113-11

Found - ½" steel tube with alum. cap.
16" now 18" Fir, alive, N.30°E., 17.4 ft., blaze healed. We tag.
16" now 18" Fir, alive, S.21°E., 6.7 ft., blaze healed. Tagged on road side.
Decayed remnants of Hemlock stump, N.45°E., 19.8 ft. with possible portion of old blaze on piece laying on ground, burned. Mr. Lecklider was quoting wrong bearing for this tree in his renewal.

(Cont. Next Page)

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 240600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

We do not find ½" galv. I.P., monument used is rusting badly.

Set Brass cap at cor. mkd: County Surveyors Office
(Deposit old monument T 28 S R 8 W
alongside) S 5

S 8

1970

This corner lies 15 ft. West of the West edge of old Burnt Mt. truck trail. (See also C.S. File 51/242)

Fd. and used in BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #863, surveyed May/July 1975 - (DCSO records Vol. 38 Page(s) 15591-92)

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - Aug. 10, 1984 - C.S. File 62/21-35

Found - Properly mkd. 1970 DCSO brass cap set on a 1 3/8" I.P. protruding 10" above ground. Set in crumbled mound of stone. No evidence of steel tube with alum. cap is found.

16" Fir now a 24" dia. 24" high D.Fir stump covered with galv. metal cap, shows evidence of a healed blaze, bears S.21°E., 6.7 ft.

16" Fir now a 22" dia., 18" high D.Fir stump covered with a galv. metal cap, shows evidence of a healed blaze, bears N.30°E., 17.4 ft.

No orig. evidence or evidence from 1936 referencing out, is found.

We re-establish 2 ft. dia. mound of stone around base of brass cap.

New BTs- 23" D.Fir, double blazed and scribed "¼ S8 CS BT" bears S.28°E., 52.5 ft.

19" D.Fir, double blazed and scribed "¼ S5 CS BT" bears N.76°E., 87.8 ft.

FD ok by DCSO 11/1/2018, SJF & JL C.S. File 67/45-27 & C.S. File 67/46-1 for Lat-Long
Lat: 43°09'22.015773299" Long: 123°40'22.162872980"