

PRIMARY CORNER DESCRIPTION Cor. No. 6 HES 143

Alias	Description

<p>HES No. 143 by Frank D. Maxwell, surveyor (FS), under special instructions dated April 27, 1914 - Surveyed June 1914- DCSO records Vol. 28 Page(s) 12017)</p> <p>-----</p> <p>Cor. No. 6, identical with cor. H/12 of listing survey No. 6-97, a fir tree, 36" dia., mkd. and witnessed as described by the listing surveyor. I mark tree 6 HES 143 on SE face, with a blaze on NE & SW faces of the tree; from which</p> <p> A fir, 24" dia., bears S.70°45'W., 35 lks.</p> <p> A fir, 15" dia., bears N.32°45'W., 14 lks.</p> <p> Both trees blazed and scribed 6 HES 143 BT.</p> <p>Pits & mound impracticable at this and all other cors.</p>
<p>Looked for/not fd. DCSO VRT 12/1969 - C.S. 54/82-92: No trace due to road way & land clearing.</p>
<p>Maurice E. Farr, USFS - July 1975 - M56-26</p> <p>-----</p> <p>Set - 1"x36" galv. pipe with Brass cap stamped "T29S HES 143 COR. 6 PE 5188 R1E 1975" from which bears:</p> <p> A 13" fir N.62°30'E., 17.3 ft. scribed 6 HES 143 BT.</p> <p> A 7" cedar S.62°W., 90.0 ft. scribed 6 HES 143 BT.</p>
<p>Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - 9/19/1991 - C.S. File 64/17-9</p> <p>-----</p> <p>Found - A 2½" brass capon an iron pipe flush with ground. BC/IP lies in rotted remains of a D.Fir of indeterminable size, no blazes or scribing found. (Orig. Corner tree?) 1975</p> <p> 13" now 18" dia. dead W.Fir with a partially healed single blaze, illegible scribing visible, bears N.62½°E., 17.3 ft. (agrees w/rec.) 1975</p> <p> 7" now 16" dia. I.Cedar with a fully healed single blaze, bears S.62°W. 90.0 ft (agrees w/rec.) 1975</p> <p>No original BTs found.</p> <p>New BTs- 19" dia. D.Fir double blaze and scribed "6 HES 143 CS BT" bears N.70°E., 10.8 ft.</p> <p> 6" dia. D.Fir double blazed and scribed "6 HES 143 CS BT" bears S.80°W., 95.3 ft.</p> <p> 7" dia. D.Fir double blazed and scribed "6 HES 143 CS BT" bears N.31°W., 56.3 ft. measured to upright portion of pistol butt trunk.</p>
<p>1</p>