

PRIMARY CORNER DESCRIPTION Cor. No. 24 HES 143

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

HES No. 143 by Frank D. Maxwell, surveyor (FS), under special instructions dated April 27, 1914 - Surveyed June 1914- DCSO records Vol. 28 Page(s) 12024

Cor. No. 24, identical with Cor. H/19 of listing survey No. 6-97 a post mkd. and witnessed as described by the listing surveyor, in place of which I set a porphyry stone, 24x10x8", 14" in the ground, for Cor. No. 24, mkd. 24 HES 143 on NW face, with a cross (+) on top; from which
 A hemlock, 24" dia., bears N.69°00'E., 19 lks.
 A hemlock, 12" dia., bears S.32°30'E., 29 lks.
 both blazed and scribed 24 HES 143 BT.
Pits & mound impracticable at this and all other cors.

Looked for/not fd. DCSO VRT 12/1969 - C.S. 54/82-101: would fall in old logging rd

Maurice E. Farr, USFS - July 1975 - M56-26

Set - 1"x36" galv. pipe with Brass cap stamped "T29S HES 143 COR. 24 PE 5188 R1E 1975" from which bears:
 A 13" hemlock S.38°15'E., 43.0 ft scribed 24 HES 143 BT
 A 7" hemlock N.56°15'E., 55.8 ft scribed 24 HES 143 BT

Leonard Herzstein, USFS & Deputy Co. Surveyor - Witnesses: T. Wolford & Jim Landrum - 4/9/1981 - C.S. File 61/19-35

Condition report
Found - 1" IP at proportionate distance and bearing, firmly set, flush with 3 ft. dia. mound of stone. 1975
Have no record of orig. bearings and distances at corner H/19 of listing survey No. 6-97, which is now the same corner position as cor. #24 HES #143
20" hemlock root crown, N.69°E., 14.2 ft. with frag. S.M. vis. on decayed blaze (Cor H/19 of No. 6-97)
12" decayed hemlock stump, S.23½°E., 10.2 ft. with S.M. "W" vis. on reverse.
13" hemlock, S.35½°E., 42.8 ft. (Rec. S.38°15'E., 43.0 ft. with healed blaze. 1975
8" hemlock, N.56°15'E., 55.5 ft. (Rec. 55.8 ft.) with heal blaze. 1975
Corner lies 20 ft. east of centerline of Ash Creek on east edge of old cat road.