

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25, 26, 35 and 36

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GL0 survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6328)

-----  
Marked Fir, 14" dia., for the cor. to secs. 25, 26, 35 and 36, from which  
A Fir 20" dia., bears N.63°E., 21 lks.  
A Fir 18" dia., bears S.15°E., 65 lks.  
A Fir 16" dia., bears S.53°W., 7 lks.  
A Fir 10" dia., bears N.45°W., 11 lks.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: R.G. Boyd - May 13, 1959 - C.S. File 42/315-8

-----  
Determined by O.B.T.s  
40" Fir N.75°E., 16.2 ft., found scribe.  
30" Fir S.18°E., 44.8 ft.  
18" Fir snag, S.43°E., 3.6 ft., found scribe.  
12" Fir N.40°W., 7.0 ft.  
At corner point, found 12" Fir snag scribed. Set 3" x 30" Iron pipe, from which  
12" Fir bears N.61°E., 18.5 ft. mkd. S25 R3W BT.  
30" Fir bears N.81°E., 34.0 ft. mkd. S25 T29S R3W BT.  
12" Fir bears S.66°E., 36.8 ft. mkd. S36 T29S BT.  
26" Fir bears S.41°W., 13.4 ft. mkd. S35 T29S R3W BT.  
Road bears North, 75.0 ft.

Douglas Co. Surveyors Office - Larry E. Monrean, Deputy - P.E. Earle, crew - Nov. 7, 1973 - C.S. File 56/41-1

-----  
Found - 3" I.P., 10" high, shows recent breakage, from which  
34" Fir stump, 7 ft. high bears S.14°E., 42.2 ft. (Rec., orig. notes, Fir 18" S.15°E., 42.9 ft.; Markham visit, 30" Fir S.18°E., 44.8 ft.) I open face.  
40" Fir stump, bears N.58°E., 11.4 ft. (Rec., orig., N.63°E., 13.86 ft.; Markham rec., N.75°E., 16.2 ft.) Scar visible.  
12" Fir stump, bears N.48°W., 11.3 ft. (Rec. orig. notes, 10' Fir N.45°W., 7.26 ft.; Markham rec., N.40°W., 7.0 ft.)  
Rotted and burned stump bears N.49°E., 15.8 ft. (Markham rec., N.61°E., 18.5 ft.)  
30" Fir stump, bears N.81°E., 28.5 ft. (Rec. 34.0 ft.) scribing visible "S29" has been dislodged.  
12" Fir stump, bears S.69°E., 32.3 ft. (Markham rec., S.66°E., 36.8 ft.)

(Cont. Next Page)

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

26" Fir stump, bears S.54°W., 15.6 ft. (Markham rec., S.41°W., 13.4 ft.) Bark scribed "BT".  
Also find rotted remains of tree at sec. corner.  
Set Brass cap at cor. mkd: County Surveyors Office  
T 29 S R 3 W  
S 26 | S 25  
S 35 | S 36  
1973

from which a

- 34" Fir stump 7 ft. high bears S.17°E., 44.6 ft.
- 40" Fir stump 8 ft. high bears N.71½°E., 13.7 ft., scars visible.
- 12" Fir stump bears N.44°W., 8.0 ft., scar visible, grown rings show extreme slow growth.
- Rotted and burned stump bears N.58½°E., 16.4 ft.
- 12" Fir stump bears S.67°E. 35.8 ft scribed "S36 BT"
- 26" Fir stump bears S.41°E., 14.5 ft. scribed "BT".
- Rotted remains of tree bears S.52°W., 3.3 ft. (Rec. orig. survey, S.53°W., 4.62 ft.; Markham rec. S.43°W., 3.6 ft.)
- 3" I.P. shows signs of recent breakage, bears S.56°E., 3.4 ft.

BLM Dependent resurvey by Timothy J. Moore & A. Bert Skeesick, Cadastral Surveyors under Group #2033, surveyed Sept. 2002/June 2003 (DCSO rec. Vol. 55 pg(s) 21319-20)

-----

The cor. of secs. 25, 26, 35, & 36, perpetuated by Markham, in 1959, & remonumented by the Douglas Co. Surveyors Office, in 1973, monumented with an iron post, 1¼" dia., firmly set, projecting 4" above ground, with brass cap (properly) mkd. from which the remains of the orig. bearing trees

- A fir stump, 41" dia., bears N.73¼°E., 12.9 ft., with a healed blaze. (Record, N.63°E., 13.9 ft.)
- A decayed fir stump, 31" dia., bears S.16¾°E., 44.6 ft. with a previously opened and rehealed blaze. (Record, S.15°E., 42.9 ft.)
- A decayed fir stump, size indeterminate, bears S.41°W., 4.6 ft., with no marks visible. (Record, S.53°W.)
- A decayed fir stump, 12" dia., bears N.45°W., 7.3 ft. with a healed blaze.

and remains of bearing trees mkd. by Markham

- A decayed fir stump, 15" diam., bears S. 67½°E., 35.7 ft. with fragmentary scribe marks visible on a partially healed blaze.
- A decayed fir stump, 26" dia., bears S.41°W., 14.7 ft. with scribe marks BT visible on a bark blaze.

continued next page

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25, 26, 35 and 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and a reference monument set by Markham  
An iron pipe, 3" dia., firmly set, projecting 3" above ground, bears S.64½°E., 3.5 ft., with no cap or marks visible.  
and new bearing trees  
A fir, 11" dia., bears N.9½°E., 23.4 ft., mkd. T29S R3W S25 BT.  
A fir, 14" dia., bears S.17½°E., 11.7 ft., mkd. T29S R3W S36 BT.  
A fir, 15" dia., bears S.31½°W., 27.3 ft., mkd. T29S R3W S35 BT.  
A fir, 11 dia. bears N.62¾°W. 9.1 ft. mkd. T29S R3W S26 BT  
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center, unless otherwise described in the corner description.

(NAD 1983 (CORS))  
Latitude: 43°00'45.24"N  
Longitude: 123°01'17.58"W

Fd. & used on BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor and Robert H Browning, Survey Tech, Under Group No. 2157, Surveyed March/May 2007 - DCSO records Vol. 57 Page(s) 22553-4

Fd as per 2007 BLM visit, 6 ft. steel post is set 2 ft North, by D. Edwards, 3/2017 - M173-15

Ron Quimby - Crew: N. Fromdahl, R Heichel & R Vincent - 1/2018 - C.S. File 65/101-22

-----  
Condition report  
Found - DCSO Brass Cap (properly mkd)  
14" Fir N.9½°E., 23.4 ft. good scar.  
16" Fir S.17½°E., 11.7 ft. good scar.  
18" Fir S.31½°W., 27.3 ft. good scar.  
14" Fir N.63°W., 9.1 ft. (Rec. N.62¾°W.) good scar.  
41"x7' tall fir stump N.73°E., 12.9 ft. good scar.  
31"x6' tall decayed stump S.17°E., 44.6 ft. (Rec. S.16¾°E., prev opened.  
36"x3' tall stump S.41°W., 14.7 vis. scribes.  
3" iron pipe S64½°E 3.5 ft.

Note - Corner is approx. 75' south of a gravel road.  
Dec. 15½°E.