

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6330-31)

Set a Fir post for the ¼ sec. cor., from which
A Fir 8" dia., bears S.50°W., 15 lks. dist.
A Fir 10" dia., bears N.60°W., 9 lks. dist.

BLM resurvey by James J. Carlson, Cadastral Surveyor, under Group #892, surveyed June/July 1976 - (DCSO records Vol. 39 Page(s) 15847)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:
T 29 S R 3 W
¼ $\frac{S\ 13}{S\ 24}$
1976

from which
A Fir 14" dia. bears N.13°W., 38½ lks. dist. mkd. ¼ S13 BT
A Fir 15" dia. bears S.3½°E., 22½ lks. dist. mkd. ¼ S24 BT

BLM Resurvey by Dale T. Bedell, Cadastral Surveyor, under Group #1383, Surveyed May/June 1987 - (DCSO records Vol. 48 Page(s) 18376-77)

The ¼ sec.cor., monumented with an iron post, 2½" dia., firmly set, projecting 8" above ground with 1976 brass cap, from which the remains of the bearing trees mkd. by Carlson
A Fir 18" dia., bears S.3½°E., 22½ lks. dist., will illegible scribe marks on a partially healed blaze.
A burnt Fir stump 15" dia., bears N.13°W., 38½ lks. dist., with healed blaze.
and a new bearing tree
A Fir 16" dia., bears S.68°W., 29½ lks. dist. mkd. X at breast height and BT at the base.
No suitable tree available in sec. 13.

Mark Smalley - For: Roseburg Resources Co. - Oct. 1999 - M 134-8

Found - 1976 BLM BC on IP
20" Fir S.3½°E., 14.9 ft., healed.
19" Fir S.68W., 19.5 ft. scribe visible.
New BTs- 19" D.Fir S.78°E., 36.5 ft., "¼ S BT"
13" D.Fir S.32°E., 35.2 ft., "¼ S BT"

Cont.

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 640400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 3/31/2009 - C.S. File 67/28-24

Found - 1976 BLM BC/IP protruding 11" out of ground.
Bearing & distances not checked
1976 BLM D. Fir BTs
NW BT now burnt & rotted high cut stump.
SE BT now high cut stump with healed blaze.
1987 BLM D.Fir BT
SW BT now high cut rotting stump no marks visible.
1999 M134-8 D.Fir BTs
S.78°E. BT now high cut stump with scribing visible
on an unhealed blaze.
S.32°E. BT not seen or looked for.
New BTs- Bearings taken with a hand compass
5" dia., D.Fir double blazed & scribed "¼ S13 BT"
bears N.53°W., 9.3 ft.
7" dia., D.Fir double blazed & scribed "¼ S13 CS BT"
bears N.72°E., 15.3 ft.
Note - Corner lies on an E-W cut line.
At the request of Ron Rice, a search was made for
orig. BTs - nothing found.
Compass decl. 16½°E.