

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. Sec. 30 only, T29-2

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6225-26)

-----  
Set a basalt stone 15x9x6 ins., 10" in the ground for 1/4 cor. of sec. 30 only, marked 1/4 on E. face; from which  
A Fir 18" dia., bears S.25°E., 18 lks. dist. mkd. 1/4 S30 BT  
A Fir 32" dia., bears N.65°E., 86 lks. dist. mkd. 1/4 S30 BT

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - Dec. 1962 - C.S. 52/126-92

-----  
Found stone at corner and both BTs as recorded. SE BT now snag, shows scribing.  
Set brass cap at corner stone, mkd. 1/4 | S30 T29S R2W  
R3W West  
New BT - 22" R.Fir bears S.36°E., 24.5 ft. scribed 1/4 S30 CSBT  
The corner is on steep South slope.

Mark Smalley - For: Roseburg Resources Co. - Oct. 1999 - M 134-8

-----  
Condition report  
Found - 1962 County brass cap on iron pipe.  
38" Fir N.65°E., 56.8 ft. healed, orig.  
28" Fir S.36°E., 24.5 ft. healed  
Fir S.25°E., 12.0 ft. down 7 rotten orig.  
36" Fir east 25.0 ft. tagged, no record.

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor and Robert H Browning, Survey Tech, Under Group No. 2157, Surveyed March/May 2007 - DCSO records Vol. 57 Page(s) 22551

-----  
The 1/4 sec. cor. of sec. 30 only, T29S R2W perpetuated by Byron, in 1962, monumented with an iron post, 1 1/4" dia., firmly set, projecting 16" above ground, with the original stone, 13 x 6 x 9", lying alongside, mkd 1/4, and a brass cap (properly) mkd.  
from which the remains of the original bearing trees  
A fir, 42" dia., bears N.65°E., 56.8 ft., with a healed blaze.  
A decayed fir stump, size indeterminate, bears S.31 3/4°E., 11.9 ft., with no marks visible. (Record, S.25°E.)  
and bearing tree mkd. by Byron  
A fir, 29" dia., bears S.38 3/4°E., 24.3 ft., with a healed blaze.