

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. for Sec. 35

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Douglas County Surveyors Office - James W. Byron, Deputy -
May 1956 - C.S. File 47/101 and RM 1-8

Corner set at the intersection of ¼ sec. lines.
Set a 1" I.P. at corner, from which
12" Fir bears N.52°E., 12.2 ft. mkd. C ¼ S35 CS BT.
12" Fir bears S.45°E., 29.8 ft. mkd. C ¼ S35 CS BT.

Douglas County Surveyors Office - Randall Smith, Stephen
Flause crew - C.S. File 64/58-6 - March 8, 1995

Corner searched for, not found.
Found - Bent 1" I.P. out of ground in ditch of dirt road
approx. 350 ft. down hill along a cat road from
area of corner search. (source unknown)
26" dia. 5 ft. high rotting D.Fir stump with a BLM
location tag, dated 1956, tagged by Markham.
Says 0 ft. to corner set by transit. Markham was
on field crew, apparently worked for Stomar Lbr.
Co. Field notes and survey RM 1-8 do not mention
this tree.
No recorded BTs are found for corner.

David Edwards - For: Seneca Jones Timber Co. & Roseburg
Resources Co. - Jan 2005 - M 147-18

The center ¼ cor. of sec. 35 was reset using the fd.
monuments as the iron pipe & BTs per RM 1-8 no longer exist.
Set - 5/8"x30" steel rebar with alum. cap stamped "ROSEBURG
RESOURCES-LS-2339-2005"
15" Cedar N.71°E., 13.1'
9" Cedar S.89°W., 18.4'
Both scribed "T29S R4W C¼ S35 BT" measured to center of
tree at root crown.
6' steel posts 2' north & south.