

TOWNSHIP 29 RANGE 05 POINT IDENTIFIER # 100300

PRIMARY CORNER DESCRIPTION Sec. cor. 19, 30; 24 & 25 T29-6.

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6421).

Set a post for cor. to secs. 19, 24, 25, 30, from which,
B. Oak, 12" dia., bears N.10°W., 150 lks.
W. Oak, 15" dia., bears S.85°W., 175 lks.
W. Oak, 10" dia., bears N.70°E., 459 lks.
Red Fir, 15" dia., bears S.2°E., 208 lks.

Doug. County Surveyors Office - James W. Byron, Co. Surveyor
- John M. Powell & Crew - Feb. 1969 - C.S. File 54/79 -
M 37-20.

Prorated section corner.
Set - Brass Cap, cor. mkd: County Surveyor's R T29S R
Office 6 S 24 | S 19 5
1969 W S 25 | S 30 W
New BTs -13" D. Fir, S.40°W., 25.1' mkd: T29S R6W S25 CS BT
14" D. Fir, N.43°W., 30.2' mkd: T29S R6W S24 CS BT
6" D. Fir, S.56°E., 25.2' mkd: S30 CS BT
No trees to the N.E. quad.
Note - Fence cor. running north & west bears N.15°W.
28.6'.

Doug. County Surveyors Office - R. Kimberling - P. Earle -
June 14, 1977 - C.S. File 59/34-38

Found - 1969 County Surveyors Office brass cap properly mkd
bears N.68°E., 17.4' from orig. corner located
from O.B.T.

From Brass cap -
A 13" now 18" D. Fir, bears S.40°W., 25.1'.
A 14" now 22" D. Fir, bears N.43°W., 30.2'.
A 6" now 8" D. Fir, bears S.56°E., 35.3' (rec.
25.2' BT tag said 35.2'.
All BTs had double well healed blazes.

From apparent orig. corner location:
A D. Fir stump, 15" now 40", bears S.2°E., 137.3'
with prev. opened single blaze. Found scribing
"2" S30 BT.

Set - Reset Brass cap in orig. location stamped to now read:
County Surveyor's T 29 S
1969 S 24 | S 19
S 25 | S 30
Reset
1977

(Cont. Next Page)

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

(cont.)
Drove a 5/8" Iron rod with alum. cap at location where we removed brass cap. Alum. cap bears N.68°E., 17.4' stamped "CS 1977". We used already scribed BTs which now face 5/8" I.R., as follows:
A 18" D. Fir bears S.0°30'W., 13.7'.
A 22" D. Fir bears N.9°W., 28.4'.
A 8" Twin trunked D. Fir bears S.75°E., 47.9'.
All BTs have double well healed blaze.
A wire fence running W & N has cor. which bears N.15°E. 35.0'

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2940, surveyed June/Sept. 2019- (DCSO records Vol. 59 Page(s) 23996-7)

The cor. of secs. 19, 24, 25, and 30, perpetuated by Douglas County Surveyor's Office, in June of 1977; monumented with an iron post, 1" dia., firmly set, projecting 6" above ground, with a brass cap (properly) mkd. from which the remains of an original bearing tree
A decayed fir stump, 40" dia., bears S.2°E., 137.3 ft., with scribe marks 2 30 BT visible on open blaze.
and the BTs mkd. by Byron, in 1969, & reused by Douglas Co. Surveyor's Office
A fir, 22" dia., bears S.73¼°E., 48.6 ft., with a healed blaze.
A fir, 27" dia., bears S.5°W., 14.2 ft., with a healed blaze.
A fir, 34" dia., bears N.4°W., 27.1 ft., with a healed blaze.
and a new bearing tree
A cedar, 13" dia., bears N.35°E., 41.9 ft., mkd. T29S R5W S19 BT.
From this cor., a point erroneously established as the cor. of secs. 19, 24, 25, and 30, by Byron, in 1969; perpetuated by Douglas Co. Surveyor's Office, in 1977. This point was established using improper control and was not utilized for control in this survey, bears N.70°21'56"E., 17.74 ft.; monumented with an iron rod, 5/8" dia., firmly set, projecting 4" above ground, in a collar of stone, with an aluminum cap mkd. DOUGLAS CO. SURVEYOR CS 1977; from which the bearing trees mkd. by Byron
A fir, 22" dia., bears S.56¼°E., 35.9 ft., with a healed blaze.
A fir, 27" dia., bears S.37½°W., 25.4 ft., with a healed blaze.
A fir, 34" dia., bears N.41¼°W., 28.1 ft., with a healed blaze.
Continued next page

TOWNSHIP 29 RANGE 05 POINT IDENTIFIER # 100300

PRIMARY CORNER DESCRIPTION Sec. cor. 19, 30; 24 & 25 T29-6.

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

The 1969 iron post was reset by Douglas County Surveyor's Office in its original position and the erroneously established position was perpetuated with an iron rod.