

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 34 & 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6431)

Set a post for 1/4 sec. cor., from which
A B. Oak, 14" dia., bears S.89°W., 125 lks.
A B. Oak, 8" dia., bears N.80°W., 125 lks.

Gene E. Johnson, R.E. 3561 - October 1955 - C.S. File 42/32 -M 11-39

Set - A 3/4" iron rod at average dist. from cor. to 34|35 and cor. to secs. 26, 27, 34, & 35.
Corner point falls on East slope, 43' W. and 98' S. of small creek in old logging slash. From which,
24" Incense Cedar, N.26°30'E., 32.8' mkd. 1/4S BT RE 3561.
18" D. Fir, bears S.57°32'W., 30.4' mkd. 1/4S BT RE 3561.
Both trees have X above face and 3 hacks on back.

Doug. County Surveyors Office - Randall W. Smith, Party Chief - Stephen J. Flause, Note Keeper - William Spencer, Land owner, Witness - Jan. 15, 1987 - C.S. File 62/40-2

A POINT OF SURVEY DESIGNATED AS 1/4 S34 & S35 (per M 11-39)
Found - 3/4" iron rod protruding 5" above ground.
24" now 35" dia., Incense cedar with a partially healed double blaze "4" and partial scribing visible, "X" axed in bark above blazes, bears N.26 1/2°E., 32.8' (agrees with record).
18" now 30" dia., D. Fir with a fully healed double blaze and "X" axed in bark above blazes, bears S.0 1/2°E., 30.4' (rec. S.57°32'W., 30.4') Blazes face iron rod.

(No Original BTs found)
3/4" iron rod set in 1955 By Gene Johnson, M 11-39, is a point of survey. Monument originally set as proportionate 1/4 cor. position between 34|35. Subsequent 1957 BLM resurvey shows position of section corner to south set in by John Markham (C.S. File 40/259) in error. 3/4" iron rod used as 1/4 cor. position in 1969 surveyed by Douglas County Surveyors office to subdivide sec. 35. (M 37-44)
Corner lies on east slope approx. 50' west of small creek.

Fd & used by Bentz, 9/90, M 110-61

continued next page

TOWNSHIP 29 RANGE 05 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 34 & 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2795, surveyed July/Aug. 2015- (DCSO records Vol. 59 Page 23577)

The ¼ sec. cor. of sec. 34 and 35, reestablished at proportionate measurement by Johnson, in 1955; there is no remaining evidence of the original cor., and is accepted as a careful and faithful reestablishment of the cor., monumented with an iron rod, 3/4" dia., firmly set, projecting 4" above ground, from which bearing trees mkd. by Johnson

A cedar, 40" dia., bears N.28¼°E., 32.9 ft., with a healed blaze.

A fir, 29" dia., bears S.2¾°E., 30.4 ft., with a healed blaze.

At the corner point

Set a stainless steel post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd.

T 29 S R 5 W

¼
S 34 | S 35
2015

Corner is located alongside the cor. of fence lines extending E., S., and W.

NAD 1983 (2011)

Latitude: 43°00'20.054"N. Longitude: 123°15'59.085"W.