

PRIMARY CORNER DESCRIPTION SE Cor. Willis DLC #41

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Bowman and Burnett, under Contract dated Sept. 1855

Set post marked as per instructions from which
A W.Oak 18" bears N.7½°W., 91 lks.

Arthur Boyer, D.C.S. - Wit: V.Phipps, F. Stephens, R.L. Moore and N.E. Richardson - March 10, 1937 - C.S. File 30/12; Vol. 4 Pg. 39 (and "old" corner book, pg. 194)

Reestablished from stump of original Oak BT. Set Ford rear axle shaft, pinion gear attached, from which
A 24" Cedar bears S.35°W., 43.2 ft. near R. bank creek.
A 22" W.Fir bears S.5°E., 47.3 ft. near R. bank creek.

Survey by Victor McLind - For: Willis Creek Properties - July 1971 - M 42-33

Reestablished from found BTs, as follows
24" Cedar now 34" stump, bears S.35°W., 43.2 ft. (near R. bank of creek)
22" W.Fir now 28" stump, bears S.5°E., 47.3 ft. (near R. bank of creek) Found part of rotted face with scribes.
Set 5/8" iron rod at corner.
Blazed and scribed New BT as follows
18" W.Oak on right creek bank, bears S.43°W., 55.3 ft. scribed "T29S R6W C 41".

BLM resurvey by Peter Peterson and Daniel Berry under Group #750, surveyed July/Aug. 1971 (DCSO records Vol. 36 Page(s) 14619-20)

The SE cor. of Claim 41, perpetuated by Boyer in 1937, from original evidence no longer in existence, monumented with an iron rod, ½" dia., firmly set, protruding 4" above ground, from which bearing trees marked by Boyer in 1937
A Fir stump 28" dia., bears S.5°E., 71 lks. dist., with healed blaze.
A Cedar stump 38" dia., bears S.35°W., 65 lks. dist., with no marks visible on rotted blaze.
and a bearing tree of no record
A W.Oak 23" dia., bears S.41°W., 82 lks. dist., with scribe marks T29S R6W C41 BT visible on partially healed double blaze.
At the corner point
Set an iron post, 28 ins. long, 2 1/2 ins. dia., 26 ins. in

(Cont. Next Page)

