

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 047030

PRIMARY CORNER DESCRIPTION Int. NW Cor. Rice DLC #47

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Bowman and Burnett, under Contract dated Sept. 1855

Set a post on Sec. line between Secs. 8 and 9, from which
A W.Oak 6" dia., bears N.4°W., 121 lks.
A W.Oak 14" dia., bears N.40°E., 158 lks.

Arthur Boyer - Feb. 24, 1940 (no record source located) (See "old" corner book, pg. 199)

Found the original 12" W.Oak N.4°W., 121 lks. and an old W.Oak stump on edge of County road N.27°E., 94 ft. which Harrison Rice said was a BT. (the original on this is N.40°E., 158 lks.) found also a 20" W.Oak already scribed and N.70°W., 100 ft.
Drove a 3/4" galv. Iron pipe 30" long for corner.

Douglas Co. Surveyors Office - James Byron, Deputy - Ray Irving, J. Fee, crew - Dec. 23, 1954 (filed Dec. 10, 1957 from incomplete survey) - C.S. File 49/40

Both BTs as set by Boyer, alive.
The NW BT face is partly rotted.
I scribe 8" W.Oak N.6°W., 78.9 ft. "Int. L. CL CS BT".

BLM survey by Robert J. Chappel, under Group #1616, surveyed June/Sept. 1991 (DCSO records Vol. 50 Page(s) 18893)

The interior corner on the W. bdy. of Donation Land Claim No. 47, perpetuated by L.G. Hicks, Private Engineer in 1917, recorded in Douglas County Surveyor's Office, map file No. M 13-71, and further perpetuated by Byron in 1954, determined at record distance from bearing trees recorded by Hicks:
An Oak 22" dia., bears N.11°E., 122 lks. dist., with scribe marks visible on sawed open blaze.
An Oak 28" dia., bears N.65°W., 121 lks. dist., with scribe marks visible on sawed open blaze.
No permanent monument established.

Douglas County Surveyor's Office, Randall Smith, Stephen Flause, Nov. 1, 1994 - C.S. File 64/52-13

Found -
3/4" I.D. iron pipe, 6" below ground. (erroneously set by Boyer in 1940 renewal)
Accessories Found -
-Both orig. BT's now gone.
(Cont. Next Page)

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 047030

PRIMARY CORNER DESCRIPTION NW interior 'L' DLC #47

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Accessories Found continued -

- 10" now 22" dia. W.Oak with a previously opened blaze with illegible scribing found, bears N.11°E., 80.5 ft. (agrees with rec.) 1917
- 12" now 28" dia. W.Oak with a fully healed double blaze, bears N.67°W., 79.9 ft. (agrees with rec.) 1917
- 8" now 12" dia. W.Oak with a fully healed double blaze bears N.7°E., 79.5 ft. - this BT erroneously tied to 3/4" I.P. by Byron in 1954.
- 3/4" I.P. bears N.89½°E., 21.0 ft. 1954 Byron.

Monument set - A 2 3/8" dia. brass cap on a 1 3/8" x 32" long iron pipe at a position determined from bearing trees in 1917 Hicks renewal. BC/IP set 2" below shoulder. Brass cap marked: DOUGLAS COUNTY SURVEYORS

T 29 S
R
6 _____ DLC
W
1994
OFFICE

Note - I believe in 1940 Boyer erroneously tied into a 1917 Hicks BT (N.11°E., 80.5 ft.) thinking it to be an 1855 original BT (N4°W., 79.9 ft.) Boyer set a 3/4" I.P. at a position 21 ft. easterly of the original 1855 corner. This renewal attempts to remonument the position of the original DLC corner using BT's from 1917 Hicks survey which had an original BT to determine the corner position from. (See map in C.S. File 64/52)

No new Accessories were set.

Note - Corner lies in easterly shoulder of Rice Creek Road near edge of pavement.