

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 17

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6486)

-----  
Set ¼ sec. post at average dist., from which  
A B.Oak 12" dia., bears N.30°E., 25 lks. dist.  
A B.Oak 8" dia., bears S.12°E., 36 lks. dist.

Frank Cain - Survey for Richard Pittman - May 14, 1914 - Field Book 33 Page 43 (and "old" corner book, pg. 194)

-----  
Trees do not fit notes. Set post N.30°E., 25 lks. from 18" Oak and remark same. Find Oak N.72°E., 66 ft. I mark a Fir 40" dia. N.3°W., 75 lks.

Arthur Boyer - Feb. 24, 1940 (no record source found) (see "old" corner book, pg. 199)

-----  
Found - Orig. Oak BT, N.30°E., 25 lks. which Cain remarked in 1913 but all of (?) at blaze is decayed.  
Set a 1½" x ¼" x 24" steel spring leaf, from above orig. BT, on fence line on E. side of road.  
A 40" Fir N.3°W., 75 lks., Okay Cain, in present road grade.  
Marked:  
A 12" Fir N.81°20'W., 76.5 ft. (chained on slope) "¼ S8 T29S R6W CS BT."  
A 30" Fir on lower side road R/W bark blazed and scribed, S.21½°W., 71.5 ft. marked "¼ S17 T29S R6W CS BT".

Cadastral survey by Hans W. Thielsen and C. Albert White under Group #s 348 and 350. Surveyed, July 23, 1958 to Aug. 5, 1959 (DCSO records Vol. 30 Page(s) 12835)

-----  
The ¼ sec. cor., perpetuated with a steel spring leaf, firmly driven in the ground, located in a woven wire fence which bears N. and S. The Douglas County records show that this spring leaf was set by Boyer in 1940, from evidence of the original survey. This point is locally accepted as the original corner.

At the corner point  
Set an iron post, 28 ins. long, 2 ½ ins. dia., 20 ins. in the ground, with brass cap marked

S 8  
¼ S 17  
T 29 S R 6 W  
1958

from which the remains of trees marked by Boyer:  
A sawed Fir stump 14" dia., bears N.81¼°W., 105 lks. dist., mkd. BT on bark.

(Cont. Next Page)

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 240500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 17

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A sawed Fir stump 30" dia., bears S.21½°W., 106 lks. dist., no marks remain.  
and new bearing trees:  
A Maple 10" dia., bears N.81°E., 190 lks. dist., mkd. ¼ S8 BT.  
A Fir 14" dia., bears N.45°W., 126 lks. dist., mkd. ¼ S8 BT.  
There is no tree available in sec. 17.  
Bury spring leaf alongside the iron post.

Fd. OK, by Howard Johnstone, Dec. 1989, M 101-72

DCSO-GIS Corner visitation - 8/20/2004 - Typed: 2/1/2011 - C.S. File 67/33-1

-----  
Monument - GLO/BLM 2.5" BC/IP  
Comment - (needs) rehab

Fd brass cap, Mark Heimburger, 2/2007 - M148-58  
Grid N: 520094.180  
Grid E: 4137558.380  
Latitude 43°03'21.9601"  
Longitude -123°25'58.9683"  
Convergence -2°00'23.89  
Scale Factor 0.99989653

Carl Sweeden - For: Harrison Rice - 1/2016 - M170-48 A&B

-----  
Condition report  
Found - 1958 BLM BC in toe of Co. Rd. fill slope in wire fence.  
14" D.Fir BT stump, N.81¼°W., 69.3' **now gone.**  
30" D.Fir stump, S.21½°W., 69.96' very rotted remains in Co Rd shoulder of fill slope, has tag.  
10" Maple BT, N.81°E., 125.40' **now gone.**  
14" D.Fir BT, N.45°W., 83.16' **now gone.**