

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 240600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6487)

Set ¼ sec. post at average dist., from which
A B.Oak 14" dia., bears N.71½°E., 31 lks. dist.
A B.Oak 16" dia., bears S.30°W., 28 lks. dist.

Arthur Boyer, Deputy County Surveyor - Wit: Chas. Vortilla and Douglas Rice - Aug. 18, 1941 - Vol. 4 Pg. 83; C.S. file 35/27 (and "old" corner book, pg. 199)

Drove 1¼" pipe at corner, marked 2 new BTs. SW ¼ Sec. 5 will be burned over so marked trees outside of fire danger.
A 20" Fir S.40°E., 47.5 ft. on slope "¼ S8 T29S R6W CS BT" on bark.
A 36" Fir N.89°E., 80 ft. on slope "¼ S5 T29S R6W CS BT" on bark.

Douglas Co. Surveyors Office - James Byron, Deputy - Dale McFarland, John Powell, crew - March/April 1962 - C.S. File 49/139-38

Found - Both BTs as recorded by Boyer, 1941. The NE BT is now down, shows good bark faces but I do not find scribing.
The SE BT now stump, shows faint scribe mark on bark.

This area has been logged and burned. Corner is at fence corner. We do not find I.P. set for corner by Boyer.

Set Brass cap at cor. mkd: County Surveyors Office

T 29 S R 6 W

¼ $\frac{S}{S}$
 5
 8

1962

New BT - 7" Laurel bears N.46½°W., 16.5 ft. scribed ¼ S5 CS BT.

No trees near to South.

BLM Resurvey, by Dale B. Bedell, Surveyed under Group No. 1714. Surveyed July - October 1994. (D.C.S.O. records Vol. 52 Page(s) 19675-76)

(Cont. Next page)

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 240600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 5 & 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

From the 1/4 sec. cor. of secs. 5 and 8, reestablished by Hicks in 1917, perpetuated by Boyer, Deputy County Surveyor, in 1941, and further perpetuated by Byron, Deputy County Surveyor, in 1962. The Hicks corner falls within acceptable position tolerances for the time of his survey,

has been accepted and used by several private surveyors and is recognized by local landowners and is, therefore, accepted as a faithful reestablishment of a lost original corner; monumented with an iron post, 1 1/4 ins. diam., firmly set, projecting 3 ins. above the ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T29S R6W

1/4 $\frac{S}{S} \frac{5}{8}$

1962

from which the remains of a bearing tree mkd. by Boyer

A burned and decayed fir, size indeterminate, bears S.42°E., 71 lks. dist., no visible marks.

and the remains of a bearing tree mkd. by Byron

A madrone snag, 18 ins. diam., bears N.49½°W., 24 lks. dist., no visible marks.

and new bearing trees

A fir, 7 ins. diam., bears N.10½°E., 29 lks. dist., mkd. 1/4 S5 BT.

A fir, 12 ins. diam., bears S.78°W., 35½ lks. dist., mkd. 1/4 S8 BT.

The corner is located at the intersection of wire fences extending S., W., and N. 5° W.

Fd brass cap, Mark Heimburger, 2/2007 - M148-58