

PRIMARY CORNER DESCRIPTION SE Cor. McCullough DLC #46

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Bowman and Burnett, under Contract dated Sept. 1855

Set a post, from which
A W.Oak 8" dia., bears S.70°W., 10 lks.
A W.Oak 14" dia., bears S.30°W., 17 lks.

Douglas Co. Surveyors Office - Ben B. Irving - James Byron;
Ray Irving - Work done for request by County Court for Road
survey, Rd. #38 - 1954 - C.S. File 46/36

Stump of O.B.T. (out of ground, stump hole) S.70°W., 10 lks.
Drove 3/4" x 36" Iron rod at corner.
New BTs -10" Fir N.73°E., 21.8 ft. mkd. C 46 CS BT.
14" Fir N.60°W., 68.7 ft. mkd. C 46 CS BT.

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J.
Flause - 1/14/98 - C.S. File 64/79-6

Found - 3/4" iron rod flush with the ground at fence
corner. 1954
No OBTs found
NE BT from 1954 renewal not found.
10" now 16" dia., 1 ft. dia., rotted D.Fir stump
no blazes or scribing found, bears N.73°E.,
21.8 ft. (agrees with rec.) 1954
New accessories -
Southeast corner of a 2.2'x1.3'x1.6' above ground
green metal electric service box bears S.86°W.,
59.3 ft.
11" dia., D.Fir, double blazed and scribed "SE DLC
46 CS BT" bears N.43°E., 41.7 ft.
12" dia., Madrone, double blazed and scribed "SE
DLC 46 CS BT" bears N.27½°W., 34.1 ft.
Northwest corner of enclosed two car garage
approx. 100' East of house, bears S.10°E.,
141.9 ft.
See sketch in file.
Note - Corner lies at the intersection of fences running
N-E-W.