

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 300540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6538)

-----  
Set 1/4 sec. post, from which  
A Laurel 14" dia., bears N.24°E., 25 lks. dist.  
A Laurel 18" dia., bears N.80°W., 30 lks. dist.

Douglas Co. Surveyors Office - Frank Cain, May 11, 1913 - Field Book 63 Pages 52-56 and CS File 6/26

-----  
A Red Fir 24" dia., S.65°30'E., 95 lks.  
A Red Fir 12" dia., S.40°W., 10 lks.

Douglas Co. Surveyors Office - Ben B. Irving; James W. Byron - Ray Irving - Work done for County Engineer, Rd. #38 - Feb. 1954 - C.S. File 46/36

-----  
Corner renewed from BT, A 36" Red Fir, S.65°30'E., 62.7 ft. BT in good condition. Red Fir S.40°W., 6.6 ft. down.  
Set a 5/8" x 30" iron rod for the 1/4 corner.  
Blazed and scribed two new trees:  
Red Fir 8" dia., bears S.87°E., 31.5 ft. mkd. 1/4 S9 CS BT.  
Red Fir 6" dia., bears S.80°W., 134 lks. mkd. 1/4 S8 CS BT.

GL0 resurvey by Hans W. Thielsen under Group #316, Surveyed, July/Aug. 1955 - (DCSO records Vol. 28 Page(s) 11771-72)

-----  
The 1/4 sec. cor., perpetuated with an iron rod, 5/8" dia., 6" above ground, set by the County Surveyor in 1954.  
From which bearing trees mkd. by Cain in 1913:  
A Fir 36" dia., bears S.65 1/2°E., 95 lks. dist., mkd. with a healed blaze.  
A turned out Fir 30" dia., bears S.40°W., 10 lks. dist., mkd. with a healed blaze.  
and bearing trees mkd. by the County Surveyor in 1954:  
A Fir 8" dia., bears N.87°E., 47 lks. dist.  
A Fir 6" dia., bears S.80°W., 20 lks. dist.  
At the cor. point  
Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap marked:  
$$\begin{array}{c} \frac{1}{4} \\ S8 | S9 \\ 1955 \end{array}$$
  
from which new bearing trees:  
A Fir 25" dia., bears S.42 1/4°E., 50 lks. mkd. 1/4 S9 BT.  
A fir 22" dia., bears S.60°W., 33 lks. mkd. 1/4 S8 BT.  
Reset the rod alongside the iron post.

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 300540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 8 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - John M. Powell and crew - Oct. 19, 1970 - C.S. File 49/139-133 ----- Found - 1955 GLO brass cap at ¼ cor., properly mkd. Also, iron rod alongside. GLO BT, 25" D.Fir N.42½°E., (Rec. S.42½°E) 33.0 ft. shows good scar. GLO BT, 22" D.Fir now down, S.60°W., 21.8 ft. Co. BT, 8" D.Fir now 10" S.87°E., 31.5 ft. shows good scar. No trace of SW bearing tree. (County) New BT - 6" D.Fir S.76°W., 30.2 ft. scribed "¼ S8 CS B".
Fd. brass cap & 6 references, BLM survey by Daniel Berry and G. Steven Popken, 1973 (DCS0 records, Vol. 39 Pgs 15804-05)
Fd. OK, Dec. 1990, M 111-17 Fd. OK, Feb. 1993, Donald Bentz, M 116-49 FD. Ok by D. Edwards, 1/2008 - M155-3
Fd. as per renewal by N. Hibbs, 1/2013 - M157-69