

PRIMARY CORNER DESCRIPTION SE. Cor. Rawson DLC #39

Alias 041030 Description SW Cor. Dryer DLC #41
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

DLC Survey by J.A. Burnett, under Contract #75 dated Nov. 22, 1856 - DLC Volume, Page 582 and Page 584

(Page 582) -----

SE. Corner Claim #39, from which

A Cedar 12" dia., bears N.65°W., 176 lks.

(Page 584)

Set a post from which

A Fir 14" dia., bears N.10°E., 374 lks.

Ben B. Irving, Deputy Co. Surveyor - Wit: W.S. Crear; C. McCann; Wm. Porter - Dec. 1927 - Vol. 3 Pg. 281; C.S. File 7/38; M 1-63

Identified and set from stump of original BT, scribe marks plainly visible.

Set Iron rod ½" x 1" x 36" for corner in North of side of county road. Marked new BT:

A 16" Cedar N.25°W., 114 lks. scribed Cl. 41 CS BT.

Survey by Herbert Northcraft - For: N. Brown - Oct. 1970 - M 42-13

Found - 1" iron rod 2" below surface of black top.

3 Witness trees scribed "S.W. Cor. Cl. 41 BT LS 750":

2' W.Oak N.58°W., 91.0 ft.

3' Fir N.1°E., 131.5 ft.

16" Cedar N.40½°E., 60.2 ft.

(3' Fir cut by landowner (Burger) Dec. 1983. Stump with scribing left.)

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - 12/8/1999 - C.S. File 66/16-3

Found - A search with a metal detector indicates a buried metal object under asphalt near north edge of Main Camas Rd. (Co. Rd. #131 W); sound signature of object is consistent with a buried iron rod (Rec. from 1927 renewal - a ½x1x36 inch iron rod)

Possible evidence of orig. NE BT fd., A large, but mostly rotted Fir stump (no evidence or face or scribing), near orig. bearing & dist.

No evidence of 1927 renewal tree fd, location falls under small house NW from monument (house is on pier foundation, stump evidence may still exist)

Evidence of 3 renewal BTs from 1970 Northcraft renewal fd.

continued next page

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 039020

PRIMARY CORNER DESCRIPTION SE. Cor. Rawson DLC #39

Alias 041030 Description SW Cor. Dryer DLC #41

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

A 3' Fir now approx. 30" dia., 2 ft. tall sawn and rotted Fir stump with no scribe marks fd. bears N.1°E., 131.5 ft. dist. (As per rec.)

A 16" Cedar now a 22" dia., 1½' tall Cedar stump with no scribing visible and which now forms the westerly half of a double stump bears N.40½°E., 60.2 ft. dist. (as per rec.)

A 2' W.Oak now 31" DBH W.Oak with a fully healed double blaze bears N.58°E., 91.0 ft. dist. (as per rec.)

Note - Due to location under asphalt, assumed monument is left as fd.

New BOs- From 1970 Northcraft survey (M42-13) A 5/8" iron rod (5/8"x30" I.Rod per survey) bears North 13.5 ft. (as per rec.)

A 2 inch "X" chiseled in top of raised concrete curbing at north side & east end of bridge of Main Camas Rd. crossing the middle fork of the Coquille River bears N.88°W., 101.0 ft.