

PRIMARY CORNER DESCRIPTION NE. Cor. G.W. Day DLC #43

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

DLC Survey by J.A. Burnett, under Contract #75 dated Nov. 22, 1856 - DLC Volume, Page 587

Set a POST, from which
An Ash 6" dia., bears S.55°W., 25 lks.

F.C. Frear, Deputy Co. Surveyor - For; S.H. Croy & M.E. Langston - April 7, 1919 - Vol. 3 Pg. 57; Field Book 46

(Frear's survey show tie to 2 rocks, 0.64 chs. apart, labeled NE. Cor. DLC 43 and SE. Cor. Claim #42)

James Byron and crew - For: E.P. Standley - Dec. 6, 1963 - M 27-13

Set 3/4" I.Rod flush, from which
A 25" R.Fir bears N.33°E., 60.2 ft. scribed NE DLC 43 CSBT
A W.Oak bears N.61°W., 108.6 ft. scribed NE DLC 43 CS BT.

Roger E. Patitz, Oreg. Dept. of Transportation - Sept. 2, 1986 - C.S. File 63/9-32

CORNER REPORT ONLY
Survey in Vol. 3 Pg. 57 states that a stone is set at the corner. No other record indicates anything else.
Found 1" Iron rod, 4" above ground. No BTs found.
This monument does not appear to be the SE. corner of DLC #42 as this corner is designated as a stone and there is no record of a pin or rod being set at the corner location. Originally thought to be the SE Cor. DLC #42. Evidence found does not substantiate this possibility.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - April 7, 1987 - C.S. File 62/40-7

Found - An unrecorded concrete nail set flush in asphaltic surface of Burma Road. Bearing trees indicate nail is set over 3/4" iron rod corner monument set by Byron in 1963. We do not disturb road surface to search for 3/4" I.R.
No original evidence found.
25" Red Fir now a 36" DBH D.Fir with a fully healed double blaze, bears N.33°E., 60.2 ft.
A W.Oak now a 27" DBH W.Oak with a fully healed double blaze bears N.61°W., 108.6 ft.

(Cont. Next Page)

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 042040

PRIMARY CORNER DESCRIPTION NE. Cor. G.W. Day DLC #43

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Bearing objects found: (Not of record)
A 1" Iron pipe protruding 2" above the ground and a
1" Iron pipe protruding 4" above (taller pipe set
by property owner, R. Halterman, to mark position
of shorter pipe - property owner believes pipes
mark road R/W, no record of pipe being set found
at DCSO.) The 1" I.P. protruding 2" above ground
as mentioned, bears N.81°E., 30.63 ft.

Fd. OK, March 1991 - M 111-69
Fd. OK, March 1996 by B. Rogers - Partition Plat 1997-0033
Fd. 2 BTs & hot reading in A/C by N Hibbs 6/2008 2008-0081A-B