

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6600)

Set ¼ sec. post, from which
A Cedar 6" dia., bears N.10°W., 39 lks. dist.
A Fir 15" dia., bears S.22°E., 13 lks. dist.

A. Boyer - March 29, 1939 - C.S. File 16/25

Set 1¼" dia., 24" long. from which
30" Fir black blaze, "¼ S29 T29-8 CS BT", bears N.8°E., 55 ft.
8" Laurel "¼ S32 T29/8 CS BT", bears S.38°E., 118.8 ft.
Corner in center CCC road.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - Oct. 1958 - C.S. File 49/100-42

Found - 1¼" Iron rod and both BTs as scribed by Boyer.
30" Fir, now 34" Fir stump, N.8°E., 55.0 ft., no scribing found, cut low.
8" now 12" Laurel, blaze not grown over, parts of scribing visible, S.38°E., 118.8 ft.
1¼" Iron rod at corner is in center of graveled road and about 3" under surface.
New BTs- 10" Cedar bears N.12½°E., 53.2 ft. scribed ¼ S29 CS BT.
7" R.Fir bears S.65°E., 56.9 ft. scribed ¼ S32 CSBT.

BLM resurvey by A. Bert Skeesick, Cadastral Surveyor under Group #1972, surveyed April/May 2001- (DCSO rec. Vol. 54 Page(s) 20958-9)

The ¼ sec. cor. of secs. 29 & 32, reestablished by Boyer, in 1939 and further perpetuated by Byron, in 1958. There is no remaining evidence of the original corner, therefore this point is accepted as the cor.; monumented with an iron pipe, 1" dia., firmly set flush with surface of Burma Road, with no cap, from which the remains of bearing trees mkd. by Boyer
A sawed fir stump, 32" dia., bears N.6¼°E., 55.9 ft., with no marks visible.
A decayed madrone stump, size indeterminate, bears S.38°E., 118.8 ft., with no marks visible.
and bearing trees mkd. by Byron
A cedar, 21" dia., bears N.11¼°E., 52.9 ft., with a healed double blaze.
continued next page

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A fir, 14" dia., bears S.66½°E., 56.9 ft., with a healed double blaze.
At the corner point
Drive an aluminum cap, 3½" dia., on top of iron pipe, mkd.
T29S R8W
¼ S 29
S 32
2001
from which
The NW. cor. of a frame house, 20 X 50 ft., bears S. ½° W., 164.3 ft., long side bears south.
Corner is buried 3" below road surface.

BLM Dependent resurvey by Timothy J. Moore & A. Bert Skeesick, Cadastral Surveyors under Group #2097, surveyed Sept. 2004 (DCSO rec. Vol. 55 pg(s) 21288-9)

The ¼ sec. cor. of secs. 29 & 32, monumented with an iron pipe, 1" dia., firmly set, buried 3" below the broken paved surface of Burma Road, with aluminum cap mkd.
T29S R8W
¼ S 29
S 32
2001
from which the remains of bearing trees mkd. by the Douglas County Surveyors Office in 1939
A sawed fir stump, 32" dia., bears N.6¼°E., 55.9 ft., with no marks visible.
A decayed madrone stump, size indeterminate, bears S.38°E., 118.8 ft., with no marks visible.
and bearing trees mkd. by the Douglas County Surveyors Office in 1958
A cedar, 21" dia., bears N.11¼°E., 52.9 ft., with a healed double blaze.
A fir, 14" dia., bears S.66½°E., 56.9 ft., with a healed double blaze.
and an accessory reported by Skeesick
The NW. cor. of a frame house, 20x50 ft., bears S.½°W., 164.3 ft., long side bears South.

Fd. BC & 4 BTs. by Gary Smither, 7/2007 - M153-78