

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6593)

Set 1/4 sec. post, from which
A Fir 50" dia., bears N.1/2°W., 53 lks. dist.
A Fir 20" dia., bears N.1/2°E., 87 lks. dist.

C.W. Crocker, Oregon State Hwy. Dept. - Sept/Dec. 1939 - C.S. File 16/55

Set a 3/4" x 30" Iron rod from a 50" orig., in good condition, N.1/2°W. and a 20" Fir, down but in good condition, orig., N.1/2°E., and at near bottom of steep North hillside. Marked and blazed two new trees as follows:
A 30" Hemlock bears N.70°30'W., 55.7 ft.
A 48" Fir bears S.46°E., 37.6 ft. scribed on bark.

Douglas Co. Surveyors Office - John M. Powell, and crew - March 23, 1967 - C.S. File 54/38-14

Found - 1/2" I. Rod at 1/4 corner.
30" now 33" Hemlock N.70 1/2°W., 55.7 ft., shows good scar.
48" D.Fir S.46°E., 37.6 ft., bark scribed "1/4 S10 CS BT"
Set Brass cap alongside I.R. mkd: County Surveyors Office
T 29 S R 8 W
1/4 S 9 | S10
1967
New BT - 15" Cedar S.37°E., 11.4 ft. mkd. 1/4 S10 CS BT.

Douglas County Surveyors Office - Gary L. Langlitz, Deputy and crew - March 20, 1978 - C.S. File 59/46-60

Found - A 1/2" I.R. and a 1967 DCSO brass cap.
An orig. 20" now 40" Fir, down and rotten with scribing "1/4 S9 BT" visible on unhealed blaze, bears N.1/2°E., 57.4 ft.
An orig. 50" now 60" D.Fir, down, no marks visible, bears N.1/2°W., 35.0 ft.
A 30" now 36" Hemlock, alive with well healed double blaze bears N.70 1/2°W., 55.7 ft.
A 48" D.Fir with bark scribing "1/4 S10 CS BT" visible on double blaze, bears S.44°E., 39.4 ft. (Rec. S.46°E., 37.6 ft. dist. is good to face.)
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 10

Alias	Description

<p>A 15" now 18" R.Cedar with scribing "4S1C" visible on partially healed double blaze, bears S.37°E., 11.4 ft. No new monument set. New BT - A 12" I.Cedar scribed "¼ S10 CS BT" on a double blaze, N.55°E., 143.7 ft. The Fir and Cedar BTs in the SE. quad. will be cut in the future during clearing for a new power line.</p>
<p>Fd. Sept. 26, 1986 by OSHD - C.S. File 63/9-35</p>
<p>BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #1027, surveyed May 1980/Aug. 1982 - (DCSO records Vol. 44 Page(s) 16999) ----- The ¼ sec. cor., perpetuated and recorded by Boyer in 1939, and further perpetuated and recorded by Powell in 1967, monumented with an iron post, 1¼" dia., firmly set, projecting 8" above ground, with brass cap mkd. in 1967 from which the remains of an original bearing tree: A root hole bears N.½°W., 53 lks. dist., with down Fir alongside, 55" dia., with no marks visible. and a bearing tree mkd. by Boyer: A Hemlock 33" dia., bears N.70½°W., 84½ lks. dist., with fragmentary scribe marks visible on partially healed blaze. and a bearing tree mkd. by Powell: A sawed Cedar stump 20" dia., bears S.37°E., 17½ lks. dist. with healed blaze. and an unrecorded bearing tree: A Cedar 17" dia., bears N.52°E., 216 lks. dist., with fragmentary scribe marks visible on open blaze.</p>
<p>Fd. OK, May 1993 by L. Jay - M 117-22</p>
<p>Fd. Brass cap in poor condition, leaning to the North, by Christine Blevins, ODOT, 4/1998 - M 129-36</p>
<p>Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 7/13/1999 - C.S. File 66/12-9 ----- Found - 2½" brass cap on a 1½" O.D. iron pipe top leans 1½ ft. north of plumb, protruding 6" above ground. Properly marked. 1939 ½" dia., iron rod protrudes 8" above ground source unknown. IR found along south edge of plumb position of BC/IP continued next page</p>

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 400540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

30" now 37" dia., 4 ft. high Hemlock stump with a fully healed single blaze and metal top, bears N.70½°W., 56.8 ft. (rec. N.70½°W., 55.7 ft. dist. Fits for a face measurement) 1939
48" now 44" dia., 3 ft. high D.Fir stump, no scribing visible bears S.46°E., 39.4 ft. (Rec. S.46°E., 37.6 dist. good to face) 1939
15" now 24" dia., 2 ft. high Cedar stump with a fully healed blaze, bears S.37°E., 11.4 ft. (agrees w/rec) 1967
Evidence of OBTs now gone area falls within bulldozed trail under power line.
17" now 24" dia., Cedar with a fully healed double blaze, bears N.52°E., 142.6 ft. (agrees w/rec) 1982 BLM
Set - BC/IP returned to plumb position, protrudes 10" above ground.
14" dia., Hemlock double blazed & scribed "¼ S9 CS BT" bears N.24°W., 41.9 ft.
15" dia., Hemlock double blazed & scribed "¼ S10 CS BT" bears S.70 3/4°E., 69.2 ft.
Note - Corner lies on a steep South slope on West edge of power line cut.