

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 and 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Page(s) 6768)

Set post cor. secs. 20, 21, 28 and 29, from which
A Fir 24" dia., bears S.4°E., 31 lks.
A Fir 10" dia., bears N.76°W., 36 lks.
A Laurel 15" dia., bears N.45°E., 50 lks.
A Laurel 12" dia., bears S.60°W., 26 lks.

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol. 16 Page(s) 6800 and 6858)

(Page 6800)
The cor. of secs. 20, 21, 28 and 29, nearly obliterated. No trace is found of the post and the SW. bearing tree has fallen and decayed. The other bearing trees are deeply overgrown.
(Page 6858-59)
I re-establish the cor. in its original position as follows:
Set a granite stone 18x10x10 ins., 12" in the ground, marked with 2 notches on S. and 4 notches on E. edge, from which
A Madrone 24" dia., bears N.46°E., 50 lks. dist. mkd. T30S R2W S21 BT.
A Madrone 14" dia., bears S.35°E., 52 lks. dist. mkd. T30S R2W S28 BT.
A Madrone 12" dia., bears S.60°W., 26 lks. dist. mkd. T30S R2W S29 BT.
A Fir 14" dia., bears N.80½°W., 36 lks. dist. mkd. T30S R2W S20 BT.

Douglas Co. Surveyors Office - John M. Powell, J. Heritage & W. Penley, crew - Dec. 1968 - C.S. File 54/73-66

Found - Orig. 10" now 17" D.Fir, N.76°W., 23.8 ft., shows good scar.
Orig. 12" Laurel now down, S.60°W., 17.2 ft., found reverse scribing not enough to call letters and rotted.
Orig. 24" D.Fir now down, S.4°E., 20.5 ft., rotted.
Orig. 15" Laurel now snag, N.45°E., 33.0 ft., shows faint scar.

Set Brass cap at cor. mkd: County Surveyors Office
T 30 S R 2 W
S 20 | S 21
S 29 | S 28
1968

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 and 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

New BTs- 6" D.Fir S.58°W., 35.6 ft. mkd. T30S R2W S29 CS BT
9" Cedar S.70°E., 32.6 ft. mkd. T30S R2W S28 CS BT
19" D.Fir N.64°E., 36.0 ft. mkd. T30S R2W S21 CS BT
Corner stone not found.

Douglas Co. Surveyors Office - Stephen J. Flause; T.R.
Franssen, crew - March 19, 1991 - C.S. File 64/13-14

Found - A 2½" dia. 1968 DCSO brass cap on a 1½" O.D. Iron
pipe, firmly set and protruding 1 ft. above
ground. No evidence of original corner monument
found.

A 24" Fir now a 28" dia. down, out of position,
broken and burned snag with a possible burned
healed blaze, the root hole of which bears
S.04°E., 20.5 ft. (Orig. BT)

A 10" Fir now a 24" dia. 4½ ft. tall burned Fir
stump with a fully healed double blaze bears
N.76°W., 23.8 ft. (orig. BT)

No evidence of the NE. and SW. orig. BTs found.

6" D.Fir now an 8" dia. down, ut of position, burned
snag with a fully healed double blaze, the root
hole of which bears S.58°W., 35.6 ft.

New Accessories:

An 8" DBH D.Fir scribed "T30S R2W S28 CS BT" on a
double blaze, bears S.03°E., 46.8 ft.

An 8" long boat spike, stamped "BO 1" on top
surface, driven in top of a 32" dia. 2 ft. tall
Pine stump, bears S.27 3/4°W., 65.2 ft.

An 8" long boat spike, stamped "BO 2" on top
surface, driven in top of a 40" dia. 3½ ft. tall
Fir stump, bears N.05°W., 25.0 ft.

Monument lies 50 ft. West and approx. 15 lower than BLM Rd.
#30-2-