

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. for Sec. 4 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol. 15 Page(s) 6200) (Duplicate Pg. 6824)

Set a slate stone 20x12x8 ins., 15" in the ground for 1/4 sec. cor. marked 1/4 on N. face, from which
A Fir 60" dia., bears N.15°W., 16 lks. dist. mkd. 1/4 S33 BT
A Cedar 12" dia., bears S.20°W., 48 lks. dist. mkd. 1/4 S4 BT.

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6218-19)

Intersect the 1/4 sec. cor., which is a slate stone, firmly set, marked and witnessed as described by the surveyor general. I change this cor. to refer to sec. 4, T30 R2W only by destroying all marks referring to sec. 33 and marking 1/4 on S. face, from cor.
A Fir 32" dia., bears S.20°E., 37 lks. dist. mkd. 1/4 S4 BT. (New BT)
A Cedar 14" dia., bears S.20°W., 48 lks. dist. mkd. 1/4 S4 BT. (Old BT)

Douglas Co. Surveyors Office - John M. Powell, J. Heritage & W. Penley, crew - Nov. 1968 - C.S. File 54/73-43

Found - No trace of stone at corner.
32" D.Fir, now stump, S.20°E., 24.4 ft., opened for scribe.
14" now 26" Cedar S.20°W., 31.9 ft., shows good scar
Set Brass cap at cor. mkd: County Surveyors Office
T 29 S
T 30 S R2W 1/4 S 4
1968
New BT - 6" Hemlock S.2°E., 19.0 ft. mkd. 1/4 S4 CS BT.
This corner lies 42.2 ft. East of 1/4 cor. S.33, T29-2.

Douglas Co. Surveyors Office - L.E. Monrean; P.L. Earle; J.H. Cook - Dec. 18, 1975 - C.S. File 57/39

Found - Brass cap laying 6" under surface in large pit caused by uprooted tree. Cap is 1968 DCSO, properly mkd. cap.
32" D.Fir now 52" dia. stump bears S.20°E., 24.4 ft. to blaze, partial scribing on blaze.
14" Cedar now 23" dia., bears S.20°W., 31.9 ft. has good blaze. (Cont. Next Page)

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 340700

PRIMARY CORNER DESCRIPTION North 1/4 Cor. for Sec. 4 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

6" Hemlock now 8" dia., bears S.2°E., 19.0 ft. has good blaze.
Reset brass cap at ¼ corner, marked as noted. This corner lies 43.7 ft. East of ¼ sec. cor. 33 T29-2. (Rec. 42.2 ft.) SET 12" dia., Cedar post 5 ft. long, 2 ft. into ground approx. 1.5 ft. North of corner monument.
The corner falls in large pit caused by uprooted Fir.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2232, Surveyed Oct. 2008/April 2009 - (DCSO records Vol. 57 Page(s) 22646)

The ¼ sec. cor. of sec. 4 only, on the N. bdy. of the Tp., perpetuated by the Douglas County Surveyor's Office in 1968 and 1975, monumented with an iron post, 1¼" dia., firmly set, projecting 1" above ground, with brass cap (properly) mkd. from which the remains of an orig. bearing tree
A sawed cedar stump, 26" dia., bears S.20°W., 31.7 ft., with no marks visible.
and the remains of a bearing tree mkd. by Strickler in 1917
A sawed fir stump, 52" dia., bears S.20°E., 24.4 ft., with scribe marks ¼ visible on an opened blaze.
and a BT mkd. by the Douglas County Surveyor's Office in 1968
A hemlock, 20" dia., bears S.5°E., 19.4 ft., with a healed blaze.
and a new bearing tree
A cedar, 9" dia., bears S.73¼°W., 22.2 ft., mkd. ¼ S4 BT.
Corner is located on a broken N. slope, in a large roothole.