

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol. 16 Page(s) 6844)

Set a granite stone 12x8x6 ins., 8" in the ground for ¼ sec. cor. marked ¼ on N. face, from which
A Fir 24" dia., bears N.14½°E., 15 lks. dist. mkd. ¼ S3 BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: O.A. Keatley - March 24, 1960 - C.S. File 42/421-16

Determined by O.B.T.s:
30" Fir N.14½°E., 9.9 ft.
30" Fir stump, logged S.42°E., 20.0 ft. (Note: Markham says this is an O.B.T., but is not listed in field notes given to me. 12/2/96 V.Laugen)
At corner point Set 3/4" x 30" Iron pipe, from which
7" W.Fir S.67°E., 10.1 ft. mkd. ¼ S10 BT.
13" W.Fir N.57°E., 22.0 ft. mkd. ¼ S3 BT.
6" W.Fir N.21°W., 8.8 ft. mkd. ¼ S3 BT.
7" W.Fir S.21°W., 15.9 ft. mkd. ¼ S10 BT.

Douglas Co. Surveyors Office - Gary L. Langlitz, P. Earle - Dec. 1974 - C.S. file 57/12-6

Found - 3/4" I.P. buried and disturbed by recent logging activity.
An orig. 24" Fir now a 24" stump, peeled, treated with preservative and covered with metal roofing. We also find a 30" Fir stump with an old, well healed scar. The orig. notes call for only one BT, the aforementioned capped stump. We do not open.

We also find Markham's bearing trees.
Set 1" x 30" I.P. with brass cap attached mkd:
County Surveyors Office

T 30 S
1/4 $\frac{S \ 3}{S \ 10}$
R 2 W
1974

We deposit the found I.P. alongside and note the existing Bearing trees:

An orig. 24" Fir now a 24" stump, bears N.14½°E., 9.9 ft.

A 30" Fir stump bears S.42°E., 20.0 ft.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

- A 7" now 11" W.Fir bears S.63°E., 10.1 ft. (Rec. S.67°E., 10.1 ft.) alive and well healed.
- A 13" W.Fir now a 15" stump, bears N.57°E., 22.0 ft., well healed.
- A 6" W.Fir now a 10" stump bears N.21°W., 8.8 ft., illegible scribing visible on damaged face.
- A 7" now 11" W.Fir bears S.21°W., 15.9 ft., alive and well healed.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2232, Surveyed Oct. 2008/April 2009 - (DCSO records Vol. 57 Page(s) 22657-8) (added 10/2011)

The ¼ sec. cor. of secs. 3 & 10, perpetuated by Markham, Jr., in 1960, subsequently perpetuated by the Douglas County Surveyor's Office in 1974, monumented with an iron post, 1¼" dia., firmly set, projecting 1" above ground, (with the orig. granite stone, 4x6x8" (Record, 6x8x12") mkd. ¼ on a face, lying nearby) with brass cap (properly) mkd.

- from which the remains of the orig. bearing trees
- A sawed fir stump, 25" dia., bears N.14½°E., 9.9 ft., with no marks visible and metal cover.
 - A sawed, decayed fir stump, size indeterminate, bears S.42½°E., 19.8 ft., with a healed blaze.
- and bearing trees mkd. by Markham, Jr.
- A fir, 22" dia., bears S.64¼°E., 10.0 ft., with a healed blaze.
 - A fir, 23" dia., bears S.20°W., 15.6 ft., with a healed blaze.
 - A roothole bears N.20¼°W., 8.8 ft.
- and a new bearing tree
- A fir, 9" dia., bears N.51¼°W., 16.9 ft., mkd. ¼ S3 BT.
- Bury orig. stone alongside the iron post

Fd As per 1974 DCSO renewal, by T. Hostetter 4/2011 - M162-29