

PRIMARY CORNER DESCRIPTION SE Cor. F.O. Worley DLC #49

Alias	Description

<p>Original - GLO survey by Bowman and Burnett, under Contract dated Sept. 1855 (DLC survey Volume, Page 614</p> <p>-----</p> <p>Set a post marked, from which A Laurel 4" dia., bears N.38°W., 22 lks.</p>
<p>GLO survey by Wm Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records DLC Volume, Pgs 717-18)</p> <p>-----</p> <p>A Laurel post, marked C 49 probably set by the Co. Surveyor; the stump of a Laurel, agreeing in size, bearing and distance between it and the post, according to the field notes furnished me, is standing. I replace the somewhat decayed post by a Laurel post, 4½ ft. long, 4" dia., 24" in the ground, marked T30S R4W C49 on NW. face, from which A Fir 40" dia., bears West, 15 lks. dist. mkd. T30S R4W C49 BT.</p>
<p>F.C. Frear, Deputy Co. Surveyor - For: H. &amp; A. Wollenberg Ranch - Nov. 1918 - M 1-3; Vol. 3 Pg. 29; C.S. File 7/18; FB 45 Pg. 68</p> <p>-----</p> <p>1½"x36" I. pipe for SE cor. F.O. Worley C. 49 set at new 4" cedar stake with 40" Fir BT probably set by CS - Laurel gone but stump still in. (Information added from FB 45 Pg. 68 7/8/2003, DCSO JC)</p>
<p>(Symbol on old visual renewal map says "looked for, not found" but no DCSO file source found - probably a county search)</p> <p>-----</p> <p>Looked for, not found.</p>
<p>Neil Hibbs - For: Douglas Wagner - May 2003 - M 137-63</p> <p>-----</p> <p><b>Condition Report</b></p> <p>Found - 1½" iron pipe set by Frear 1918 Orig. BT is gone.</p> <p>Note - Fd. 1½" IP looks to be of same age as other monuments of Frear that were fd. but is sticking up out of ground, unlike the others that were fd. flush with the ground surface. Location is also skeptical because distance between this monument and the SW cor. of DLC 49 is over 28 ft. short.</p>
<p>Fd. 1" Iron pipe, 3/2013 - R. Quimby, M157-70</p>