

PRIMARY CORNER DESCRIPTION NW Cor. Jacob Amsler DLC #51

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor, June 8, 1857
-(DCSO records, DLC Volume, page 617)

NW cor. which is a Fir 10" dia. on right bank of S. Umpqua
River in Sec. 25, R4W, from which
 An Oak 18" dia., bears S.80°W., 14 lks.
 A Fir 30" dia., bears N.50°E., 4 lks.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract
#535, dated Feb. 5, 1889 (DCSO records DLC Volume, Page 722)

The Fir 10" dia., as marked for this corner, has decayed, but
both the bearing trees are standing. I restore this corner
by setting a basalt stone 16 x 8 x 7 ins. 12" in the ground
marked 51 on the SE. face, from which
 A B.Oak 21" dia., bears S.80°W, 14 lks. dist. mkd. T30S
 R4W C.51 BT.
 A Fir 36" dia., bears N.50°E., 4 lks. dist. mkd. T30S R4W
 C.51 BT.

These are the old bearing trees whose dim marks, I renew.
(The cor. of secs. 23, 24, 25 and 26 bears from this corner,
N.34°W., 4.80 chs. dist. making Claim corner, 3.98 chs. South
and 2.68 chs. East of sec. corner.)

Ben B. Irving, Deputy Co. Surveyor - Wit: J.I. Irving; V.N.
Poole - March 8, 1930 - C.S. File 37/18 and M 1-37

Location identified from Fir BT which I remark.
Oak BT figures rotted out but position checks.
Drove spike into root for corner.
 A 36" Tan Oak N.50°E., 39 lks. mkd N.W. Cor. Cl. 50 CS BT.

Douglas Co. Surveyors Office - James Byron, Milo Godfrey,
Mike Darby, crew - Aug/Sept. 1963 - C.S. File 53/26-107

Found - Orig. 30" now 54" R.Fir N.50°E., 2.6 ft., shows
 scribing.
 Now 40" Tan Oak N.53°E., 21.7 ft. not N.50°E. 25.7 ft
 Do not find spike set at corner by Irving, 1930.
Set R.R. spike on top of large root of orig. Fir BT, spike
driven to 1" above surface.
New Accessories:
 11" Maple bears S.42°W., 17.6 ft. scribed NW DLC 51
 CS BT.
 Set 3/4" I.R. in fence line and at old gate post
 bears N.80°E., 38.9 ft.

(Cont. Next Page)

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 051010

PRIMARY CORNER DESCRIPTION NW Cor. Jacob Amsler DLC #51

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #1070, surveyed June 1981/May 1982 - (DCSO records Vol. 43 Page 16807)

The NW. corner, perpetuated and recorded by Irving in 1930, and further perpetuated and recorded by Byron, in 1963, determined at record bearing and distance from the face of the remaining original bearing tree:

A Fir 52" dia., bears N.50°E., 4 lks. dist., with scribe marks C 51 visible on bark blaze.

and a bearing tree mkd. by Irving

A Tan Oak 44" dia., bears N.55°E., 32 lks. dist., with healed blaze.

and a bearing tree mkd. by Byron

A Maple 13" dia., bears S.40°W., 29 lks. dist., with healed double blaze.

At the corner point

Set an iron pipe, 16" long, 1" dia., in drill hole in root of the original bearing tree, with brass tablet, 3¼" dia., 3½" stem inserted in iron pipe, with top mkd: T 30 S R 4 W

S 25 |
 | C 51
 | 1982

Fd. Ok by Kristian DeGroot - 11/2006 - M146-49

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 2/17/2010 - C.S. File 67/31-4

Condition report only

Found - BLM brass cap iron pipe in large root of an orig. BT. BT now 20' high snag with a fully healed blaze facing BLM BC/IP. Old bark scribing found on north trunk "S2 T30S RW 30 1"

RE tag 1930 tan oak with healed blaze & 1963 maple. 1963 I.R. fd. 2½ ft. below ground.

Note - Corner lies on easterly bank of South Umpqua River. Compass decl. 16½°E.