

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 140200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 30 and 31

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 17 Page(s) 7123)

Set a stone 16x14x10 ins., 12" in the ground for ¼ sec. cor., marked ¼ on N. face; from which

A Fir 10" dia., bears S.30°E., 14½ lks. dist. mkd. ¼ S BT.

A Fir 14" dia., bears N.71°E., 38½ lks. dist. mkd. ¼ S BT.

Survey by Robert M. Thompson - April 15, 1956 - C.S. File 42/152

Found - An Iron pipe here that does not check with original BTs.

Original corner stone still in place.

Orig. BT, a 17" D.Fir N.71°E., 25.0 ft. in good condition.

The other orig. BT, is a rotted stump.

Scribe new BT:

16" D.Fir S.12°E., 20.5 ft.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. S. Stoffel crew - Aug. 1963 - C.S. File 53/26-84

Found - Stone at corner.

Orig. 14" now 17" R.Fir N.71°E., 25.0 ft., shows scribing.

Find stump, rotted, of orig. SE. BT.

1" I.P. that bears S.55°E., 19.0 ft. from true corner. This pipe apparently set from a 14" R.Fir that shows scar from injury, not axe. Do not find scribing.

Thompson's 16" R.Fir S.12°E., 20.5 ft. is OK, shows good scribing.

Reset 1" I.Pipe alongside corner stone.

No new trees scribed.

Survey by Mark Smalley - For: Roseburg Resources - May 20, 1991 - M 113-18

Found - Stone and 1" I.P. set by Byron in 1963.

14" Fir stub N.71°E., 25.4 ft., rotted.

16" Fir stub S.12°E., 20.5 ft., rotted.

New BTs - 6" Fir S.52°E., 34.3 ft. scribed "¼ S31 BT"

4" Fir S.25°E., 22.3 ft. scribed "¼ S31 BT"

No trees within reasonable distance on rock bluff to North.

continued next page

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 140200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 30 and 31

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Ken Hoffine - For: Lone Rock Timber Co. - Nov. 2013 - M 166-6 & C.S. File 65/81-1

Condition report only.

Found - 1" iron pipe 1.0 ft above ground w/stone alongside
Rotten remains bears N.73½°E., 26.7 ft (record N.71°E., 25.4 ft) no visible marks.
Rotten remains bears S.11½°W., 21.5 ft (record S.12°E., 20.5 ft) no visible marks.
15" D.Fir bears S.31¼°E., 21.9 ft (record S.25°E., 22.3 feet) healed face.
13" D.Fir bears S.55¼°E., 33.4 ft (record S.52°E., 34.3 ft) healed face

Corner lies on top of South edge of rock bluff.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2872, surveyed April 2017/Oct. 2019- (DCSO records Vol. 59 Page 23847-8)

The ¼ sec. cor. of secs. 30 & 31, perpetuated by Thompson, in 1956; subsequently perpetuated by Byron, in 1963, further perpetuated by Smalley, in 1991. reported by Hoffine, in 2013; monumented with an iron pipe, 1 1/4" dia, firmly set, projecting 11 ins. above ground (alongside of which is the original basalt stone 14 x 14 x 10 ins., firmly set, projecting 11 ins. above ground, with illegible marks visible on the north face, from which the remains of an original BT
A decayed fir stump, 17" dia., bears N.71°E., 25.4 ft., no marks visible.

and the remains of a BT mkd. by Thompson

A decayed fir stump, 20" dia., bears S.11¾°W., 21.3 ft., no marks visible.

and the BTs mkd. by Smalley

A fir, 16" dia., bears S.55°E., 33.8 ft., with a healed blaze.

A fir, 15" dia., bears S.31°E., 21.9 ft., with a healed blaze.

At the corner point

Set a stainless steel post, 28" long, 2½" dia., 21" in the ground, directly over the iron pipe, 24" long, with BC mkd.

T30S R4W

¼ S30
S31

2017

from which

A fir, 14" dia., bears N.84½°E., 37.2 ft., mkd. ¼ S30 BT.
Buried the original stone, 14x14x10", alongside the stainless steel post. (Record, 16x14x10")