

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 240700

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. for Sec. 5 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

John H. Markham, Jr. - Wit: Geo. Vaughn and Don Weathers -
April 7, 1951 - C.S. File 40/296-4

This corner was never set by government. At midpoint on township line, I SET a 1" x 24" iron pipe, from which
A Fir 12" dia., bears S.21°E., 109.0 ft. mkd. ¼ S S5 BT.
A Laurel 20" dia., bears S.52°W., 73.0 ft. mkd. ¼ S5 T30S R4W 2880 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel crew - May 1963 - C.S. File 52/126-139

Found - 1" I.Pipe at corner.
20" Laurel S.52°W., 73.0 ft., shows scribing.
SE BT, now stump.
New BT - 11" W.Oak bears S.64°E., 88.0 ft. scribed ¼ S5 CS BT

BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor, and Robert Browning, Surveying Technician, under Group #1686, surveyed May 1993 thru April. 1995 - (DCS0 records Vol. 52 Page(s) 20096-7)

Point for the ¼ sec. cor. of sec. 5 only, at midpoint of the N. bdy. of the section.

Set a stainless steel post, 28" long, 2½" diam., 25" in the ground, with brass cap mkd.

T29S R4W
¼ S 5
T30S R4W

1994 from which

A fir, 5" diam., bears S.19 3/4°E., 14½ lks., mkd. ¼ S5 BT

A fir, 11" diam., bears S.77°W., 40½ lks., mkd. ¼ S5 BT.

Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.

From this point, a point established as the ¼ sec. cor. of sec. 5 only by Markham, in 1951, perpetuated by Byron, in 1963, bears South, 0.152 chs.; monumented with an iron pipe, 1" diam., firmly set, projecting 6" above ground, from which the remains of bearing trees mkd. by Markham:

A decayed fir stump, size indeterminate, bears S.20°E., 166 lks., with no marks visible.

A madrone, 24" diam., bears S.55 3/4°W., 109 lks., with no marks visible.

and a bearing tree mkd. by Byron

An oak, 12" diam., bears S.64 3/4°E., 133 lks., with healed blaze.

It was determined that Markham used proper control in an east and west position and improper control in a north and south position, therefore, this point was rejected. _____