

PRIMARY CORNER DESCRIPTION Sec. Cor. 32, 33; 4 & 5 T31-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 17 Page 7134)

-----  
Set a post at proper distance, for cor. to secs. 4, 5, 32 and 33, from which

- A Laurel 16" dia., bears N.23°W., 63 lks. dist.
- A Laurel 18" dia., bears S.33°W., 68 lks. dist.
- A R.Fir 24" dia., bears S.47°E., 83 lks. dist.
- A Pine 13" dia., bears N.16°E., 24 lks. dist.

-----  
GLO resurvey by W. P. Wright under Contract #281 dated May 16, 1878 (DCSO records, Vol. 19 Page 7889)

-----  
Have seen no signs of a surveyed line after careful examination. At 40 chs. from 1/4 Cor. 32 & 33, found post, set by County Surveyor, which post I made the cor. to secs. 4, 5, 32 and 33, from which

- A Laurel 64" dia., bears N.85°E., 6 lks.
- A Laurel 14" dia., bears N.67°E., 44 lks.
- A Laurel 12" dia., bears S.52°W., 30 lks.
- A Laurel 14" dia., bears N.72°W., 34 lks.

-----  
Douglas Co. Surveyors Office - Floyd J. Cole, Deputy - 1915/1916 - Vol. 2 Pg. 248, FB. 64 Pg. 9 & M 6- 19

-----  
corner to secs. 4, 5, 32 & 33 (as witnessed by Co. Surveyor via 4 Laurels - per Field book)

- Laurel 24" N.74°W., 23 lks.
- Laurel 24" N.75°E., 6 lks.
- Laurel 24" S.69°E., 34 lks.
- Laurel 12" S.52°W., 38 lks. (Info added 3/7/2001 DCSO)

-----  
A. Boyer, Surveyor - Cooper and Ted Ross, Witnesses - Cavander Survey - Sept. 23, 1938 - C.S. File 16/45

-----  
Located from orig. Laurel to NW (N.23°W., 63 lks.)

Set 4 x 4 post Fir.

New trees are:

- 8" Fir N.63°E., 24 ft.
- 10" Fir S.35°W., 11.5 ft.
- 10" Fir S.83°E., 14 ft.

-----  
Doug. County Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam - Nov. 12, 1959 - C.S. File 46/64; M 1-9

-----  
Found - All of Boyer's BTs. The SW BT, now snag only. All show good scars and all check bearing & distance.  
(Cont. Next Page)

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32, 33; 4 & 5, T31-5

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Also find ½" x 12" iron rod at corner.  
Set Brass cap alongside iron rod and mkd:  
County Surveyors Office  
S32 | S33 T30S  
S 5 | S 4 T31S R5W  
1959  
New BTs -16" R.Fir bears West 70.5 ft. scribed S32 T30S R5W  
CS BT.  
9" Laurel bears S.87°E., 79.2 ft. scribed S4 T31S  
R5W CS BT.  
48" Cedar bears S.38°W., 100.7 ft. scribed S5 T31S  
R5W CS BT.  
This area badly burned this year.

Doug. County Surveyors Office - James Byron, Deputy - Mike  
Darby; Jim Halterman - Nov. 1963 - C.S. File 53/26-38  
-----  
Found - Brass cap at corner and all BTs as recorded. All  
bearing trees now snags.  
New BTs -16" R.Fir bears N.86°W., 71.1 ft. scribed S32 T30S  
R5W CS BT.  
18" Laurel bears N.70°E., 86.4 ft. scribed S33 T30S  
R5W CS BT.  
16" R.Fir bears S.66°E. 35.7 ft. scribed S4 T31S R5W  
CS BT.

Corner found OK by BLM resurvey by Jelley, Roseberry, and  
Brooks, under Group #'s 320 and 614 - Surveyed June 1966/May  
1968 (DCSO records, Vol. 35 Pages 14365-66)

Doug. County Surveyors Office - Larry E. Monrean, Deputy -  
F.C. Silagy, witness - June 27, 1978 - C.S. File 60/11-20  
-----  
Found - 1" I.P. with attached DCSO brass cap properly  
marked. Monument is approx. 14" high & firmly  
set. Did not find iron pipe.  
1858 BT, fragmentary remains around root hole of a  
rec. 64" Madrone bearing N.85°E., 4.0 ft. to the  
area of the apparent face.  
1858 remains of a badly decayed Madrone (Fd. no  
scribing or blaze). Root hole bears S.52°W., 19.8  
ft.  
Fir 8" now a 12" stump 3½ ft. high bears N.63°E.,  
24.0 ft. scribed "CS BT" legible on a double  
blaze.  
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32, 33; 4 & 5 T31-5

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Fir 10" now a 13" snag, 12 ft. high bears S.35°W., 14.5 ft. to face, 15.0 ft. to center, scribing "S4 T31S R5W CS BT" visible in unhealed blaze.

Fir 10" now a 13" snag, 10 ft. high bears S.83°E., 11.5 ft. to face 12 ft. to center (Rec. 14.0 ft.) scribing "T S" visible in burned out double blaze.

Fir 16" now a 30 ft. high snag bears N.89°W., 68.8 ft. (Rec. West 70.5 ft.) scribed "T30S R5W S32 CS BT" on a partially healed double blaze.

Madrone 9" now dead with a new growth around old trunk, bears S.85°E., 70.2 ft. (Rec. S.87°E.) scribed "S 4 T31S R5W CS BT" on a double blaze.

48" Cedar now a 40 ft. high snag, bears S.38°W., 100.7 ft. scribed "S5 T31S R5W CS BT" on a single blaze.

Fir 16" now a 20 ft. high snag bears N.84°W., 75.2 ft. (Rec. N.86°W., 71.1 ft.) scribed S32 T30S R5W CS BT" on a 3 ft. high blaze.

Madrone 18" now a 19" dia., 12 ft. high snag bears N.70°E., 86.4 ft. blaze rotted out.

R.Fir bearing S.66°E., 35.7 ft. is now a tipped out snag partially rotted.

New BT - A Madrone 4" bears N.67°E., 7.2 ft. Bark scribed "S33 CS BT".

No other trees available at this time.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 3/5/2001 - C.S. File 66/21-1A-E

Found - 1959 DCSO brass cap iron pipe, protrudes 14" out of ground, mkd: COUNTY SURVEYORS OFFICE

	T30S R5W
	<u>S32 S33</u>
	S5 S6
	T31S R5W
	1959

No evidence of 1854 BTs, 2 root holes of 1878 BTs, see 1978 ren.

8" now 10" dia., 3 ft. high D.Fir rotted blaze, illegible scribing visible, bears N.63°E., 24.5 ft. (Rec. N.63°E., 24.0 ft.) (1938)

10" now rotted D.Fir remains with a burnt face, faint scribing visible "T31S R" bears S.35°W., 11.5 ft. (1938)

10" now 12" 3 ft. high D.Fir snag scribing visible "S4 T31S R5W CS BT" bears S.83°E., 15.0 ft. (Rec. S.83°E., 14.0 ft.) (1938) continued next page

Alias	Description
Alias	Description
Alias	Description
Alias	Description

- 16" D.Fir now rotted stump, bears N.89°W., 68.8 ft. (1959)
- 9" now dead & rotted snag scribing found "R5W" bears S.87°E., 79.2 ft. (1959)
- 48" I.Cedar now snag with scribing visible "T31S R5W" bears S.38°W., 100.7 ft. (1959)
- 16" now rotted D.Fir no scribing found bears N.86°W., 71.1 ft. (1963)
- 1963 NE BT not found.
- 16" now 12" dia., rotted D.Fir stump with a rotted blaze, no scribing found, bears S.66°E., 37.7 ft. (Rec. S.66°E., 35.7 ft.) (1963)
- 4" now 6" dia., Dead Madrone with illegible bark scribing, bears N.67°E., 7.2 ft. (1978)
- New - 8" dia., D.Fir, double blazed & scribed "T30S R5W S32 CS BT" bears N.13½°W., 8.8 ft.
- 6" dia., D.Fir, double blazed & scribed "T30S R5W S33 CS BT" bears N.24°E., 18.0 ft.
- 8" dia., D.Fir double blazed & scribed "T31S R5W S4 CS BT" bears S.48°E., 16.7 ft.
- 6" dia., D.Fir double blazed & scribed "T31S R5W S5 CS BT" bears S.13½°W., 7.9 ft.
- Compass Decl. 17 3/4°E.

History Narrative of section corner:

- 1854 GLO Ford survey sets post and mark 4 BTs.
  - 1875 Mineral survey by Briggs has a tie to section corner.
  - 1878 GLO Wright survey accepts post set by County Surveyor could not find 1854 line, marks 4 BTs.
  - 1916 Douglas County Deputy Cole is at section corner finds 4 BTs shows a variance in bearing & distance from 1878 rec. to BTs (Vol. 2 Pg. 248 & M 6-29)
  - 1916 GLO Skookum Mineral Survey has a survey tie to section corner and a tie to Levins Ledge Mining Claim. 1875 tie from NW cor. of Levins Ledge Mining to section corner is N.71°25'E., 1118.7 ft. 1916 GLO tie using Skookum Mineral Survey information is N.73°18'E., 1122.3 ft.
  - 1938 Boyer, (Deputy) Douglas County Surveyor locates corner from original 1854 NW BT and marks 3 BTs.
  - 1951 Markham survey C.S. 40/183 states that 2 section corners are found that fit Government notes. 1878 and 1854 corners shown as 290 ft. apart.
  - 1959 Byron, Douglas County Deputy, find ½" iron rod and 1938 BTs at corner, set brass cap/iron pipe, marks 3 BTs
  - 1963 Byron, Douglas County Deputy, find BC/IP, marks 3 BTs.
  - 1966 BLM Jelley survey finds corner OK, sets corners of Skookum Mining Claim, also set brass cap iron pipes on section lines, one of the BC/IPs is easterly 254 ft.
- continued next page

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Sec. Cor. 32, 33; 4 & 5 T31-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

1978 Douglas County Deputy Monrean finds remains of 2 1878 BTs, marks 1 BT.

2001 Douglas County Surveyors Deputy Smith finds brass cap iron pipe, marks 4 BTs.

In reviewing the history of this section corner I believe that evidence indicates historical record dating back to the orig. 1854 corner see 1938 renewal of an orig. 1854 BT being found. The corner, is monumented by a brass cap/iron pipe, has through out history been accepted as the section corner. (Note: this corner also used by Markham in 1951 as the section corner.) Randall W. Smith, Deputy DCSO. LS #2469

Fd. BC by R. Brown, 10/2013 - M166-4

FD. BC & 6 BTs by R. Quimby 6/2016 - M171-12 A&B