

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34; 3 & 4, T31-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Addison R. Flint, Under Contract #56, dated March 1855 (DCSO records Volume 17 Page 7193)

-----  
Set post, cor. secs. 33, 34, 3 and 4, from which  
A B.Oak 20" dia., bears N.18°W., 109 lks.  
A B.Oak 21" dia., bears N.30°E., 125 lks.  
A B.Oak 20" dia., bears S.85°E., 104 lks.  
A B.Oak 20" dia., bears S.26°W., 62 lks.

Original - W.H. Byars, under contract # 448 survey dated June 13, 1882 (DCSO records Vol. 19 Page(s) 7989-90)

-----  
Intersect Tp. line, 76 lks. W. of cor. to secs. 3, 4, 33 and 34, which I re-established as per notes furnished by setting an Oak post, 4 ft. long, 4" sq., 24" in the ground, mkd. T30S R6W S34 on NE.; T31S S3 on SE.; S4 on SW.; and S33 on NW. faces, with 3 notches on E. and W. edges.  
Bearing trees all standing, viz.  
A B.Oak 21" dia., bears N.30°E., 125 lks. dist. mkd. T30S R6W S34 BT.  
A B.Oak 20" dia., bears S.85°E., 104 lks. dist. mkd. T31S R6W S3 BT.  
A B.Oak 20" dia., bears S.26°W., 62 lks. dist. mkd. T31S R6W S4 BT.  
A B.Oak 20" dia., bears N.18°W., 109 lks. dist. mkd. T30S 6W S33 BT.

John H. Markham, Jr. - Wit: Harry Dayton - March 21, 1955 - C.S. File 41/370

-----  
Determined by O.B.T.s  
30" B.Oak snag bears N.11°W., 72 ft.  
25" B.Oak stump bears S.80°E., 69.0 ft.  
25" B.Oak stump hole bears N.30°E., 84.5 ft.  
25" B.Oak stump bears S.32°W., 41.0 ft.  
At corner point, Set 3/4" x 44" Iron pipe, from which  
14" Laurel bears N.74°E., 46.5 ft. mkd. "S34 BT".  
15" Laurel bears N.22°E., 17.0 ft. mkd. S34 BT".  
14" Laurel bears N.35°W., 29.0 ft. mkd. S33 BT".  
A fence corner bears S.78°W., 9.2 ft. Fences run North, south, East and West.

(Cont. Next Page)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Doug. County Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam - May 23, 1960 - C.S. File 52/25

-----  
Found - 3/4" Pipe set by Markham.  
14" Laurel N.74°E., 46.5 ft. scribe visible.  
14" Laurel N.35°W., 29.0 ft. scribing visible.  
15" Laurel N.22°E., 17 ft., down and dead.  
Blazed and scribed new trees;  
9" Fir S.2°E., 79.2 ft. mkd. "T31S R6W S3 CS BT".  
9" W.Oak S.10°W., 97.4 ft. mkd. "T31S R6W S4 CS BT".  
No trace of original BTs except stump holes and a few remnants of charred wood. All trees in immediate vicinity, including BTs, are badly damaged by fire in 1959.

Fd. OK, August 1981, George Grubb, M 88-67

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 9/20/1999 - C.S. File 66/12-29

-----  
Found - 3/4" I.D. iron pipe protrudes 10" above ground. 1955  
14" now down & rotted Madrone bears N.74°E., 46.5 ft. (Agrees with rec.) 1955  
N.35°W., and N.22°E., BTs from 1955 now gone.  
9" now 14" dia., W.Oak with a fully healed double blaze, bears S.10°W., 97.4 ft. (Agrees w/rec.) 1960  
1960 SE BT gone.  
New BTs- 13" Madrone single blazed & scribed "T30S R6W S33 CS BT" bears N.36°W., 26.0 ft.  
Double trunked B.Oak, double blazed & scribed "T31S R6W S3 CS BT" on 6" dia., Northerly trunk, center base Northerly trunk, bears S.87½°E., 14.9 ft.  
5" D.Fir double blazed & scribed "X CS BT" bears N.74°E., 53.3 ft.  
Note - Corner lies 3½ ft. north of an East-West fence line  
4-way fence corner noted in 1960 now gone.

Fd. OK by K. DeGroot, Jan. 2004 - M137-77