

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. Sec. 12

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Howard W. Johnstone - For: Roseburg Lumber Co. - Nov. 1988 - M101-44

Set - Witness corner at base of rock bluff 5 ft. south of C $\frac{1}{4}$.
5/8"x36" iron rod & alum. cap mkd: WC 5' C $\frac{1}{4}$ S12.
10" cedar, N.56°E., 16.7 ft. "C $\frac{1}{4}$ WC BT"
8" cedar S.11°E., 14.5 ft. "C $\frac{1}{4}$ WC BT"

Tony Hostetter - For: Roseburg Resources Co. Co. - May/July 2003 - M142-69

Set 2 WC corners
1st WC corner North 122 ft. of true corner:
Set - 5/8" x 30" rebar w/ 2 $\frac{1}{2}$ " alum. cap.
Scribed- "WC BT" on 12" DF, bears N.4°E., 16.1 ft.
"WC BT" on 7" DF, bears N.25°W., 17.8 ft.
2nd WC corner West 200 ft. of true corner:
Set - 5/8" x 30" rebar w/ 2 $\frac{1}{2}$ " alum. cap.
Scribed- "WC BT" on 16" DF, bears S.73°W., 10.6 ft.
"WC BT" on 11" DF, bears S.12°W., 8.5 ft.
Note - Per narrative - some corners established on M101-44 were set incorrectly. These positions were not accepted in this survey. The monuments at the W $\frac{1}{4}$ & N $\frac{1}{4}$ (M101-44) were pulled & the cap was removed & the rebar was driven under the surface at the CN1/16 position & all BT tags were removed at the request of Roseburg Resources Co. (These corners were anywhere from 40' to 80' out of position)