

PRIMARY CORNER DESCRIPTION Cor. Secs. 4, 5, 32 & 33 T30-1E

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, US Deputy Surveyor, under contract dated June 7, 1922 - (DCSO records Vol. 26 Page(s) 11195-6)

Set an iron post, 3 ft. long, 2" dia., 26" in the ground, for cor. of secs. 4, 5, 32, & 33, with brass cap mkd

T30S	R1E
S 32	S 33
S 5	S 4

T31S

1923

from which

- A fir, 38" dia., bears N.21°E., 7 lks mkd: T30S R1E S33 BT
- A fir, 38" dia., bears S.52°E., 22 lks mkd: T31S R1E S4 BT
- A fir, 30" dia., bears S.55°W., 33 lks mkd: T31S R1E S5 BT
- A fir, 36" dia. bears N.33°W., 118 lks mkd T30S R1E S32 BT

James N. Landrum USFS & Deputy Co. Surveyor - Leonard Herzstein - April 6, 1983 - C.S. File 62/10-14

Found - 2" dia. iron post, 36" long, lying on the ground with 1923 GLO brass cap marked: T30S R1E S32 S33 S5 S4 T31S 1923.

Roothole, bears N.21°E., 4.6 ft. with downed log alongside with scribe marks "T30S R1E S33" visible on partially healed blaze. Log is 40" D.Fir

Roothole, bears S.52°E., 14.5 ft. with 40" D.Fir stump alongside with healed blaze.

36" D.Fir, bears S.55°W., 21.8 ft. with healed blaze.

36" D.Fir stump, bears N.33°W., 77.9 ft. with scribe marks "R1E S32 B" visible on partially healed blaze.

Set - The orig. corner monument was knocked out of the ground when the original NE BT blew over. At a position determine from record bearings & distances of all original BTs, I RESET iron pipe 32" in the ground in a 2 ft. diam., mound of stone. I stamp "RESET 1983 L S 2024" on brass cap (5-18-83,

New BTs- 52" D.Fir, N.49°E., 41.9 ft. scribed "T30S R1E S33 CS BT" on single blaze.

6" W.Fir, S.85°E., 83.9 ft. scribed "T31S R1E S4 CS BT" on single blaze.

14" W.Fir, N.31°W., 33.7 ft. scribed "T30S R1E S32 CS BT" on single blaze.

Note - Corner is approx. 150 ft. west of USFS Road #2925-670 in USFS clearcut.