



TOWNSHIP 31 RANGE 01 POINT IDENTIFIER # 300240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

All new bearing trees have double blazed faces with a brass washer stamped "PLS 1941" nailed into the lower blaze. Bearings are taken to the center of the tree at the root crown, and distances are measured to the root crown at the side and center of the tree. Bearings and distances were measured with a staff compass (Decl. 20°E) and steel tape.

John Ransom, USFS - Jonathan Drew - 1/2014 - C.S. 65/85-11  
-----

Condition report

Found - 2½" brass cap (properly mkd) on 1¼" iron pipe, projecting 5" above a mound of stone.  
Indt dia. Pine stob (S.89°E.) (20.5 ft) rotten remains of stob, no face.  
7" W.Oak (N.25°W.) (51.8 ft) healed double blaze  
23" P.Pine (S.21°30"W.) (37.6 ft) healed single blaze.  
13" W.Oak (S.26°E.) (10.6 ft) healed single blaze  
( ) = Record per 63/138  
Brush cleared around monument and to BTs  
"LAND LINE" flagging tied on monument and guard posts.  
No new accessories added  
New nails in BT tags and painted faces & 6 inch band at head height.

Note - Corner falls on nearly level ground, about 40 feet easterly of FS road 1610-370, also falls at the SW corner of a private clear cut unit, from intersection of 300 and 370 spur drive south 1/4 mile to corner.

Property line maintained East .25 & North .25 miles