

PRIMARY CORNER DESCRIPTION Cor. Secs. 27, 28, 33, & 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, US Deputy Surveyor, contract 73 dated June 8, 1857 - (DCSO Records Vol. 18 Page(s) 7463

Set post, cor. secs. 27, 28, 33, & 34, from which
A fir, 30" dia., bears S.63°W., 65 lks.
A fir, 30" dia., bears N.50°W., 30 lks.
A fir, 24" dia., bears N.80°E., 54 lks.
A maple, 10" dia., bears S.33°E., 49 lks.

GLO survey by Fred Mensch, US Cadastral Engineer - Under special instructions dated June 7, 1922 - (DCSO records Vol. 18 Page(s) 7537-8)

The cor. of secs. 27, 28, 33, & 34, which is a badly decayed fir post, with marks indecipherable.
In place of the decayed post
Set an iron post, 3 ft. long, 2" dia., 28" in the ground, for cor. of secs. 27, 28, 33, & 34, with brass cap mkd

T31S R1W
S 28 | S 27
S 33 | S 34
1923

from which
A fir, 28" dia., bears N.81°E., 54 lks., mkd: T31S R1W S27 BT. (Old BT)
A maple, 14" dia., bears S.31°E., 48 lks., mkd: T31S R1W S34 BT. (Old BT)
A fir, 12" dia., bears S.59°W., 34 lks., mkd: T31S R1W S33 BT. (New BT)
A fir, 30" dia., bears N.44°W., 31 lks., mkd: T31S R1W S28 BT. (Old BT)

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - Sept. 1968 - C.S. File 54/71-60

Found - GLO Brass Cap, properly mkd in 1922, out of ground. 28", now 38" D.Fir, N.81°E., 35.6 ft., shows good scar.
14", now 16" Maple, S.31°E., 31.7 ft., shows scar.
30", now D.Fir Stump, N.44°W., 20.5 ft., shows good scar.

No trace of SW BT.
Reset - Brass cap at sec. cor., cap was out of ground.
New BTs- 16" D.Fir N.68°W., 17.3 ft. mkd: T31S R1W S28 CS BT.
13" Hemlock S.15°W., 51.0 ft mkd T31S R1W S33 CS BT.

continued next page

TOWNSHIP 31 RANGE 01 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Cor. Secs. 27, 28, 33, & 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Don E. Garrett - For: US Forest Service - Aug. 1975 - M58-7

Found - 1922 USGLO brass cap properly marked.
16" Maple, bears S.31°E., 31.7 ft. (9.662 meters)
16" Fir, bears N.68°W., 17.3 ft. (5.273 meters)
13" Hemlock, bears S.15°W., 51.0 ft. (15.545 meters)
NE tree down.
New BT - 14" Fir, bears N.31°E., 42.0 ft. (12.802 meters).
Scribed S27, T31S, R1W, BT.

John Ransom, USFS - Crew: Jonathan Drew - 7/28/2014 (filed 3/29/2017) - C.S. File 65/95-15

Found - 2½" brass cap on 2" iron pipe, projecting 13" above the ground, slanted slightly west.
21" fir snag N.30°E., 41.6 ft healed double blaze
Indt root hole N.81°15'E., 35.8 ft. 36" high stump
downed and dragged
21" maple S.30°45'E., 31.1 ft healed single blaze
30" fir N.69°45'W., 17.1 ft healed double blaze.
Indt fir stump N.44°15'W., 20.0 ft rotten stump,
hollow shell, log over face.
New - New accessories include a ¾" brass washer stamped
"LS2561" set flush in lower face between "B"&"T"
A 12" fir bears, S.45°45'W., - 10.3 ft, marked
"T31SR1WS33" "BT" on a double blaze.
A 11" fir bears, N.53°45'E., - 61.8 ft, marked
"T31SR1WS27" "BT" on a double blaze
Note - Corner falls about 75 feet north of private logging
road in section 34, follow FS road 370 to gate,
follow private road 2000 ft+/- west to overgrown
spur on north, follow old spur to corner on west
side.
Brush cleared around monument and to BTs "LAND LINE"
flagging tied on monument and guard posts
Property line maintained north .5 miles
Basis of bearing being platted bearing (N.0°06'45"E.)
using a property line post found to the north.
Measurements by LEICA 1103+ Total Station with red
laser to aluminum nail set at side center.

Fd as per record A DeGroot, 10/2019 - M171-70