

PRIMARY CORNER DESCRIPTION South ¼ Corner Sec. 27, only

Alias	Description

GLO survey Fred Mensch, US Cadastral Engineer - Under special instructions dated June 7, 1922 - (DCSO rec Vol 18 Pgs 7536-7)  
-----  
Set an iron post, 3 ft. long, 1" dia., 28" in the ground, for ¼ sec. cor. of sec. 27 only, with brass cap marked  
¼ S 27  
1923  
from which  
    A fir, 7" dia., bears N.27°E., 30 lks., mkd: ¼ S27 BT.  
    A fir, 7" dia., bears N.19°W., 17 lks., mkd: ¼ S27 BT.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - Sept. 1968 - C.S. File 54/71-54  
-----  
Found - GLO Brass Cap, properly marked in 1922.  
        7", now 14" D.Fir, N.19°W., 11.2 ft., shows good scar.  
        No trace of NE Bearing Tree.  
New BT - 24" D.Fir N.65°W., 35.3 ft. scribed "¼ S27 CS BT".  
Note - ¼ Corner of Section 34 only bears west 49.5 ft.  
        Also fence bears North 11.0 ft.

Fd. BC & 2 BTs by D. Garrett, 8/1975 - M58-7

John Ransom, USFS - Jonathan Drew - 1/2013 - C.S. 65/85-22  
-----  
Found - 2½" brass cap (properly mkd) on 1" iron pipe, projecting 10" above the ground.  
        23" Fir (N.19°W.) (11.4 ft) healed double blaze  
        27" Fir (N.65°W.) (35.3 ft) healed double blaze  
        2.5" brass cap (N.88°05'W.) (49.05 ft.) ¼ S34 only  
        GLO cap per M58-7.  
        ( ) = record per M58-7  
        Brush cleared around monument and to BTs  
        "LANDLINE" flagging tied on monument and guard posts  
        **No new accessories added**  
        New nails in BT tags and painted faces & 6" band at head height.  
Note - Corner falls on slight west slope, just south of old barbed wire fence, on edge of timber line with old growth to the north. To find corner, take 1610-370 about 500 ft past the 378 spur, go south on old overgrown road above rock erosion control on edge of road, follow old road to posted line, then east on line.  
        Property line maintained west 1700 ft +/- and east .5 mile