

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 700440

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 13 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7701)

Set a Fir post, 4 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor. marked ¼ S on W. face, from which
A Fir 24" dia., bears S.82°W., 52 lks. dist. mkd. ¼ S BT.
A Fir 24" dia., bears S.68°E., 70½ lks. dist. mkd. ¼ S BT

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #766, dated May 10, 1906 - (DCSO records Vol. 18 Page(s) 7620-21)

The ¼ sec. cor. is partially obliterated. The Post has decayed at the bottom and fallen down.
I reestablish the cor. in its original position for sec. 13, T31S R3W. only, as follows:
No stones obtainable.
Set a Fir post 3 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. on E. bdy. Sec. 13, marked ¼ on W. face, from which
A Fir 20" dia., bears N.68°W., 70 lks. dist. mkd. ¼ S13 BT
A Fir 24" dia., bears S.82°W., 52 lks. dist. mkd. ¼ S13 BT

James Klein - Keith Primm - Douglas Popham - For: Williams/Pacific Connector Pipeline - 5/2015 - M166-40 A-I

East ¼ corner of section 13 was not found. Said corner was a fir post 4" square and 4' long set by Bushy in 1894. A forest fire has destroyed the wood post and the original bearing trees. This point has been computed by single proportion using found original line trees as described in the original notes north and south of this corner.