

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29, 30, 31 and 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - W.H. Byars, under contract # 456 survey dated July 28, 1882 (DCSO rec. Vol. 19 Page 7931)

Set a Fir post, 4" square, 4 ft. long, 20" in ground for cor. to secs. 29, 30, 31 and 32, marked T31SR5W S29 on the NE face, S32 on the SE. face, S31 on the SW. face, S30 on the NW. face, also one notch on the South and five notches on the E. angles of same, from which

- A Fir 20" dia., bears N.23°E., 31 lks. dist., marked T31S R5W S29 BT.
- A Chinquapin 10" dia., bears S.32°E., 34 lks. marked T31S R5W S32 BT.
- A Fir 32" dia., bears S.45°W., 65 lks. dist. marked T31S R5W S31 BT.
- A Fir 18" dia., bears N.80°W., 62 lks. dist. marked T31S R5W S30 BT.

Survey by Victor S. King - For Bate Lumber Co. - Oct. 30, 1959 - C.S. File 51/56-9

- Found - 2" Post and 1 OBT with scribing.
48" Fir O.B.T., S.45°W., 56.1 ft. rescribed in bark, S31 T31S R5W BT.
New BTs - 12" Fir N.89°E., 93.3 ft. scribed S29 T31S R5W BT.
14" Fir N.63½°W., 103.8 ft. scribed S30 T31S R5W BT.
18" Fir S.10°E., 68.4 ft. scribed S32 T31S R5W BT.

Survey by Arnold G. Gibson - Wit: D. Bagger; R. Schulson; H.B. Baughn - For: Oregon State Board of Forestry - Aug. 1963
C.S. File 51/264

Original Fir stake (missing), from which
20" Fir bears N.23°E., 31 lks. now 32" stump.
10" Chinquapin bears S.32°E., 34 lks., sprouted in place.
32" Fir bears S.45°W., 65 lks., 48" uproot, face down.
18" Fir bears N.80°W., 62 lks.; now 20" stump.
Restoration by King in 1959:
Fir stake, found, not in place, from which a
12" Fir bears N.89°E., 93.3 ft.; uproot, scribed T31S R5W S29 BT.
14" Fir bears N.63½°W., 103.8 ft.; uproot, scribed T31S R5W S30 BT.
48" Fir (orig) bears S.45°W., 56.1 ft.; uproot, face down.
18" Fir bears S.10°E., 68.4 ft.; uproot, scribed T31S R5W S32 BT.
Set 1½" x 36" Galv. Iron pipe with 3" cap mkd: "Ore. St. Bd. of Forestry S29 S30 S31 S32 T31S R5W 1963 RS 359", 30" in ground, from which (Cont. Next Page)

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29, 30, 31 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

26" stump bears N.12°E., 12.0 ft. scribed T31S R5W S29 BT.
26" Fir bears S.13°W., 59.6 ft. scribed T31S R5W S31 BT RS
359.
22" Fir bears S.74°E., 180.0 ft. scribed T31S R5W S32 BT.
Set 4" x 4" x 72" white painted Cedar post 1.0 ft. SE of
corner pipe. OSFD metal location poster on 26" stump BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones
and Joe Brady - May 1966 - C.S. File 54/25-2

Found - 26" Fir now stump, S.13°W., 59.6 ft. pitched over
face.
22" Fir, now blow down, S.74°E., 180.0 ft. scribe
visible.
26" Fir stump N.12°E., 12.0 ft. scribe visible T31S
R5W S29 BT.
State Bd. of Forestry Brass cap at set cor.
New BTs -4" Chinquapin bears N.79°E., 23.7 ft. scribed S29 CS
BT.
5" Fir S.80°W., 70.2 ft. scribed T31S R5W S31 CS BT.
5" Fir S.8°E., 82.4 ft. scribed S32 CS BT.
Logging road bears South, 30.0 ft.

BLM resurvey by James Jelley and Wayne Rogers under Contract
#1101, surveyed Sept. 1982/May 1983 (DCS0 records Vol. 45
Page(s) 17492-93)

The Sec. Cor., perpetuated and recorded by King in 1949,
further perpetuated and recorded by Gibson in 1963 and by
Powell in 1966, monumented with an iron post, 1½" dia.,
firmly set, projecting 6" above the ground, with brass cap
mkd:
OREGON STATE BOARD OF FORESTRY
T 31 S R 5 W
S 30 | S 29
S 31 | S 32
1963
from which the remains of an original bearing tree
A root hole bears S.45°W., 65 lks. with downed Fir
alongside, 48" dia., with scribe marks S R5W BT visible
on bark blaze.
and the remains of bearing trees mkd. by King
A root hole bears N.89°E., 141 lks., with a down Fir
alongside, 14" dia., with scribe marks 29 31S R5W B
visible on partially healed blaze.
A root hole bears S.12½°E., 104 lks., with a down Fir
alongside, 18" dia., no marks visible.
and the remains of bearing trees mkd. by Gibson
(Cont. Next Page)

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29, 30, 31 and 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A sawed Fir stump, 36" dia., bears N.12°E., 20 lks., with scribe marks T31S R5W S29 BT visible on open blaze.
A root hole bears S.74°E. 273 lks with a down Fir alongside 24" dia., with scribe marks T31S R5W visible on partially healed blaze.
A sawed Fir stump, 26" dia., bears S.13°W., 90 lks. with scribe marks T31S R5W S31 BT visible on open blaze.
and bearing trees mkd. by Powell
A Chinquapin 8" dia., bears N.79°E., 36 lks. with healed blaze.
A Fir 10" dia., bears S.8°E., 125 lks., with healed blaze.
A Fir 12" dia., bears S.80°W., 106 lks. with healed blaze.
and a new bearing tree
A Fir 8" dia. bears N.21½°W., 11½ lks. mkd T31S R5W S30 BT
The corner is located 50 lks. North of a graveled road, 25 lks. wide, bears E. and W.

Fd. OK, by Bruce Shaner, May 1993 - C.S. File 63/153-22
Fd. Ok, by Lloyd Smith, May 1995 - M 122-17

Daren L. Cone - For: Oregon Department of Forestry - 9/1/2019 (after the July 2019 Mile Post 97 forest fire burned through the corner location) - CS File 65/104-25

Condition report only
Found - 1" iron pin flush with ground per CS 40/280
1½" iron pin protrudes 9" above ground alongside 1" iron pin per CS40/280
Steel post 2 ft south per M169-18
Steel post (unknown origin) bears S.89°30'W., 33.6' on eastern edge of gas line road
Original BT marked by Byars in 1882:
24" Fir S.6°W., 24 lks- now burned out root hole
BTs DCSO in 1966:
3" Fir N.78°W., 11.7 ft, now 16" dia x 2.5' tall stump, face healed over.
3" Fir S.21°W., 20.2 ft. (Now 14" dia x 5' tall stump, face healed over, existing BT tag.
There are no suitable trees to mark as additional bearing trees following the fire.
Note - All bearings and distances noted in this report are the record calls as recorded in the survey which established the bearing tree. This report only verified general location and condition of the bearing trees and accessories. No new Bearing trees were established this visit.
Declination 15 1/2°E