

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 243700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. Sec. 32 only T30-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 17 Page 7134)

Set a post at proper distance, from which
A Pine 6" dia., bears S.28°W., 100 lks.
A R.Fir 8" dia., bears N.87°W., 63 lks.

Doug. County Surveyors Office - James Byron, Deputy - Ray Irving; John Fee - Survey for: County Land Department - Aug/Nov. 1954 - C.S. File 46/64

Set an iron pipe with brass cap at midpoint and on true line between SE corner Sec. 32 and SW corner of Sec. 32, and marked:

County
Surveyors Office
1954 T30S R5W 32
T31S R5W 5

Blazed and scribed:
5" R.Fir S.37½°W., 29.5 ft.
10" R.Fir N.57½°E., 41.0 ft.

Doug. County Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam - Nov. 12, 1959 - C.S. File 46/64; M 1-9

Found - Brass cap at corner. I obliterate the number 5 which refers to Sec. 5 and add the word South. The cap now reads "South ¼ Corner Sec.32. I find both BTs now dead.

Chiseled 2" + (cross) and B.O. on South face of 5 ft. x 5 ft. stone outcrop, bears N.48°E., 6.7 ft.
New BT - 40" R.Fir bears North, 91.6 ft. scribed ¼ S32 CS BT. This is in 1959 burned area. Bottom of draw 100 ft. ± South of corner.

Doug. County Surveyors Office - Gary L. Langlitz, Deputy - Larry Monrean; Stephen Flauser; Frank Silagy - June 19, 1979 -C.S. File 61/3; RM 3-26

Found - Orig. Post not found.
Brass cap monument set by Byron mkd. "County Surveyors Office T30S R5W ¼ S32 T31S R5W 1954". As this monument was set by measurement dependent on position determined by Wenderoth Survey C.S. 39/118 for the southerly section corner of secs. 31 and 32, (See C.S. File 46/64
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 32 only T30-5

Alias	Description
Alias	Description
Alias	Description
Alias	Description

of the Co. Surveyors records), we do not find the position of this monument acceptable to mark the South $\frac{1}{4}$ corner of S.32.

5" Fir now dead, bears S.37 $\frac{1}{2}$ °W., 29.5 ft. We open single blaze & find scribing " $\frac{1}{4}$ S5 T31S R5W CSBT"

10" Fir now dead with a burnt out blaze with no scribing visible bears N.56 $\frac{1}{2}$ °E., 41.0 ft. (Rec. N.57 $\frac{1}{2}$ °E.)

A Chiseled "+ BO" on south face of rock outcrop bears N.48°E., 6.7 ft.

40" R.Fir scribed " $\frac{1}{4}$ S32 CS BT" on a double blaze bears North, 91.6 ft.

No original bearing trees found.

Set a 1" x 36" I.P. at position determined by proportional measurement to mark the quarter corner position. Attached brass cap on I.P. is stamped: "Douglas County Surveyor T30S R5W 1/4 S32 T31S 1979". Cap set by Byron bears S.73°27'02"E., 190.24 ft.

New Accessories:

D.Fir 16" scribed " $\frac{1}{4}$ S32 CS BT" on a double blaze bears N.4 3/4°E., 123.8 ft.

9" Madrone scribed "S 5 CS BT" on a double blaze (orientated N.19°E.), bears S.62°W., 26.7 ft.

20" D.Fir scribed " $\frac{1}{4}$ S32 CS BT" on a double blaze bears N.76°W., 47.5 ft.

We return to the monument set by Byron and obliterate the marks on the cap and remove scribing and marks from all references.

Corner lies on a steep slope running N.55°E.

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike
- 3/5/2007 - C.S. File 67/21-18

Found - 2 $\frac{1}{2}$ " dia., brass cap with all markings obliterated on 1 $\frac{1}{4}$ " O.D. iron pipe, projects 11" above ground. Set by James Byron in 1954 (M1-9)

2 $\frac{1}{2}$ " dia., brass cap mkd as per record set by DCSO on 6/19/1979 (RM 3-26) It was determined by this office to obliterate this position. See M146-53

1979 Accessories

16" now 24" dia., D.Fir, fully healed double blaze, fd as per 1979 rec.

9" now 15" dia., Madrone, mostly healed double blaze, fd as per 1979 rec.

20" now 25" dia., D.Fir, fully healed double blaze, fd as per 1979 rec.

continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 32 only T30-5

Alias	Description
Alias	Description
Alias	Description
Alias	Description

1954 Accessories
10" R.Fir now fallen & out of position.
5" R.Fir not fd.

1959 Accessories
2" Chiseled "+" and letters "B0" visible in rock outcrop. "+" bears N.44°E. 6.7 ft. (Rec. N.48°E., 6.7 ft.)
40" now 40" dia., x 12 ft. tall D.Fir snag, evidence of healed chopped out blaze, bears North, 91.6 ft. (agrees w/rec.)

New - Brass cap at Byron's position was filed smooth & re-stamped: COUNTY SURVEYOR OFFICE 2007
T 30 S R 5 W
¼ S 32
T 31 S

All markings on 1979 brass cap (Ingram's position) were obliterated and blank brass cap now becomes an accessory to newly accepted position. BT tags removed from trees witnessing the 1979 position

10" dia., D.Fir, double blazed & scribed "¼ S32 CS BT" bears N.29½°W., 32.9 ft.
11" dia., Madrone, double blazed & scribed "S5 CS BT" bears S.46½°W., 19.3 ft.
6" dia., Live Oak, double blazed & scribed "S5 CS BT" bears S.32°E., 28.3 ft.
2½" dia. brass cap all marks obliterated, flush with ground bears N.75°22'45"W., 190.22 ft.

Note - Lies on steep rocky slope.
Compass decl. 16¼°E.

FD. BC, rock outcrop & 4 BTs by R Quimby 6/2016 - M171-12 A&B
Fd. By R. Quimby 10/2018 - M175-1