

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 600140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 35 & 36

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

GLO survey by W.H. Byars under contract #727, dated December 20, 1900 - (DCSO records Vol. 19 Page(s) 8180-1)

Set a Fir post, 4 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor., marked S36 on E and S35 ¼ S on W side; from which
A fir, 10" dia., bears N.80°E., 22 lks., mkd: S36 ¼ S BT.
A cedar, 16" dia. bears S.68°W., 10 lks. mkd: S35 ¼ S BT.

Loren Swearingen - For: Robert Dollar Co. - Jan. 16, 1961 - C.S. File 51/68-5

Corner found in poor condition. The Orig. BT. for Sec. 35 is a 20" cedar which has had the face destroyed by a logging slash fire. The Orig. 10" Fir Tree for Section 36 has blown over but the orig. face is clearly visible.
I marked the corner with a 7/8"x30" Flex Drill Steel driven 20" in the ground from which I referenced
A 8" Fir N.28°W. 54.5 ft. scribed S35 ¼ 4186 BT.
A 10" Fir S.44°E. 16.9 ft. scribed S36 ¼ 4186 BT.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & J. Brady - March 1967 - C.S. File 54/32-15

Found - Orig. 14", now 18" Cedar, S.68°W. 6.6 ft., has burnt face.
8", now 10" D.Fir, N.28°W. 54.5 ft., scribe visible "¼S".
No trace of S.E. BT nor 7/8" corner rod, taken out by skid road.
Set - Brass Cap at Cor mkd: County Surveyors T31S R9W Office, 1967 ¼ S35|S36
New BT - 8" D.Fir S.69½°E. 53.2 ft. mkd. ¼ S36 CS BT.
Note - Also found stump with good BT. face, but could not determine where it came out of the ground.

BLM dependent resurvey by Francis J. Simon, Cadastral Surveyor under Group #2325, surveyed July/Nov. 2010 - (DCSO records Vol. 57 Page(s) 22755-6)

The ¼ sec. cor. of secs. 35 & 36, perpetuated by Swearingen, in 1961, from original evidence no longer in existence, and further perpetuated by the Douglas County Surveyor's Office, in 1967; monumented with a hexagonal drill steel, 7/8" across top, flat to flat, firmly set, projecting 4" above the ground, from which the remains of a BT mkd. by Swearingen
A sawed fir stump, 18" dia., bears N.27½°W., 55.0 ft., with a healed blaze.
continued next page

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 600140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 35 & 36

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

and a BT mkd. by the Douglas County Surveyor's Office
A fir, 16" dia., bears S.71 $\frac{3}{4}$ °E., 54.1 ft., with a healed blaze.

The 1967 Douglas County Surveyor's Office monument, an iron post, 1 $\frac{1}{2}$ " dia., 25" long, with brass cap mkd. COUNTY SURVEYORS OFFICE T31S R9W $\frac{1}{4}$ S35 S36 1967, was found lying loose underneath a log alongside the drill steel.

The original SW. cedar bearing tree, size indeterminate, with a burned blaze, was found uprooted and downhill to the W. of the drill steel and determined to have been disturbed from its original location due to earth disturbance by machinery.

At the corner point
Set a stainless steel post, 28" long, 2 $\frac{1}{2}$ " dia., 22" in the ground, directly over the drill steel, with brass cap mkd.

T31S R9W
 $\frac{1}{4}$
S 35 | S 36
2010

from which a new bearing tree

A fir, 11" dia., bears N.18 $\frac{1}{4}$ °W., 39.7 ft., mkd. $\frac{1}{4}$ S35 BT. Deposit a magnet in a white plastic case at the base and the Douglas County Surveyor's Office iron post horizontally alongside the stainless steel post.

(NAD 1983 (CORS 96))

Latitude: 42°49'54.15"N. Longitude: 123°43'18.24"W.