

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 13 & 14

Alias	Description

GLO survey by Charles L. Campbell, Deputy Surveyor, under Contract #747 dated May 5, 1902 - (DCSO rec. Vol. 19 Pg 8299

Set an ironstone 15x12x8", 10" in the ground for ¼ sec. cor. mkd. ¼ on W face, from which
 A hemlock, 14" dia., bears S.66°E., 18 lks., mkd: ¼ S13 BT
 A fir, 20" dia., bears S.61½°W., 31 lks., mkd: ¼ S14 BT.

Douglas Co Surveyors Office - James Byron, Deputy - Mike Darby & Wm Stoffel - March 1963 - C.S. ~~54/15~~ 53/15-1 (10/21/2020)

Found - Orig. 14" now down 20" Hemlock, shows good scribing, "¼S13 BT" S.66°E. 11.9 ft.
 Orig. SW BT not found in roadway.
Note - Corner is at South edge of roadbed.
Set - Brass Cap at Cor. mkd: County Surveyors Office, 1963
 ¼ S14|S13 T32S R2W
New BTs- 9" Yewood bears N.89°E. 32.0 ft. scribed ¼ S13 CS BT
 9" W.Fir bears S.43°W. 76.5 ft. scribed ¼ S14 CS BT.

John Ransom, USFS - Jonathan Drew - 9/2013 - C.S. 65/85-33

Found - Monument fd disturbed, 2½" DCSO brass cap on 1¼" iron pipe, pushed by cat and leaning northeast above mound of stone and below slash pile. Fd monument buried in a pile of slash pushed onto corner by cat, cut out slash over corner position and find monument leaning heavily in the direction of cat work. Corner believed to have been pushed out of position, no work done to straighten monument. Corner monument no longer in correct position, work needed to correct damage done by private logging
"LAND LINE" flagging tied on monument & guard posts
12" Yew (N.89°E.) (32.0 ft) scribe on part. healed double blaze
29" W.Fir (S.43°W.)(76.5 ft) healed double blaze
() = Record per 1963 DCSO record.
No new accessories added
New nails in BT tags and painted faces & 6 inch band at head height
Note - Corner falls on north slope and at corner of private clear cut in three directions, take forest road 1616-140 to just south of corner, only one large tree remains on private here is the BT, follow small spur road to corner, corner falls in south cut bank of said spur.

Cont.

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 13 & 14

Alias	Description

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - July 23, 2014 - C.S. File 67/41-31

Found - Orig. ironstone searched for but not fd.
A 2½" dia., brass cap (properly mkd) on a 1" I.D. iron pipe is bent and leaning S.47°E., 0.8 ft. from its plumb position and protrudes 5" above a low, rough pile of stones. 1963
Monument was partially buried under logging debris logging debris, which is removed from area.
Accessories measured from plumb position of monument:
1963 BTs- A 9" yewood now an 11" dia., Pacific Yew with partially healed double blaze still showing the scribing "¼ S13 CS" "BT"; bears N.89°E., 32.0 ft. (as per rec.)
A 9" W.Fir now a 29" dia., W.Fir with a fully healed double blaze; bears S.43°W., 76.5 ft (as per rec)
New - The plumb position of the fd BC monument is referenced out. The monument is removed (iron pipe is fd to be 36" long) The pipe is straightened and the monument is returned to the referenced plumb position. BC now plumb and protrudes 4" above the ground. The monument is surrounded by a low 2 ft. dia., mound of stone which rises 4" above the brass cap.
A 20" dia., W.Fir scribed "¼ S13" "CSBT" on a double blaze; bears N.10½°E., 37.5 ft.
An 8" long galvanized spike nail is set driven through a BT tag and protruding 1" above the top of a 23" dia., 1 ft. tall D.Fir stump. The spike and the center of the root-crown of the stump bears S.9°E., 15.8 ft.
Note - Monument is on gently northerly sloping ground with very old reprod fir n the NE quadrant. The other surrounding quadrants are mostly clearcut with scattered older reprod firs.
Compass decl. 15¼°E.