

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 12 & 13

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Charles L. Campbell, Deputy Surveyor, under Contract #747 dated May 5, 1902 - (DCSO records Vol. 20 Page(s) 8301

A fir 10" dia., for 1/4 sec. cor. mkd 1/4 S12 on the N and S 13 on the S, from which

 A fir, 30" dia., bears S.50°E., 44 lks., mkd: 1/4 S BT.

 A fir, 14" dia., bears N.1 1/2°W., 32 lks., mkd: 1/4 S BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Mike Darby & Wm. Stoffel - March 1963 - C.S. File 54/15-3

Found - Orig. 30" now 34" fir stump S.50°E., 29.0 ft. prev. opened, shows scribing.

 No trace of Orig. NW BT.

Set Brass cap at cor. mkd: COUNTY SURVEYORS 1/4 S 12 T32S R2W OFFICE 1963 S 13

New BTs- 5" R.Fir bears N.60°W., 100.0 ft scribed 1/4 S12 CS BT

 5" Fir bears S.1°W., 44.5 ft. scribed 1/4 S13 CS BT.

John Ransom, USFS - Jonathan Drew - 9/2013 - C.S. 65/85-37

FOUND - 2 1/2" DCSO brass cap (properly mkd) on 1" iron pipe, projecting 4" above a mound of stone

 28" Fir (N.60°W.) (100.0 ft) healed double blaze

 30" Fir (S.1W.) (44.5 ft) healed double blaze

 Indt. Fir stump (S.50°E.) (29.0 ft) decayed stump, detached face

 () = record per 1976 M56-68

 No new accessories added

 New nails in BT tags and painted faces & 6 inch band at head height

 Brush cleared around monument and to BTs

 "LAND LINE" flagging tied on monument & guard posts

Note - Corner falls on level ground, about 75 ft south of FS RD 1616 take 1616 RD to 1616-150 spur, park at intersection, west BT falls on west side of 1616-150 spur.

 Property line maintained east .5 miles and south .5 miles.