

PRIMARY CORNER DESCRIPTION Sec Cor for 13 & 24; 18 & 19, T32-1

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO Survey by Rufus S. Moore, Deputy Surveyor, under Contract #475, dated July 3, 1883 - (DCSO records Vol. 19 Page(s) 8246)

 Set a basalt stone 14x10x10 ins., 10" in the ground, cor. to secs. 13, 18, 19 and 24, 300 ft. below top of Umpqua divide, mkd. with 3 notches on N. and S. edges, from which
 A Yew 6" dia., bears N.50°E., 15 lks. dist. mkd T32S R1W S18 BT.
 A Fir 22" dia., bears S.23°E., 15 lks. dist. mkd. T32S R1W S19 BT.
 A Fir 10" dia., bears S.18°W., 44 lks. dist. mkd. T32S R2W S24 BT.
 A Yew 8" dia., bears N.70°W., 8 lks. dist. mkd. T32S R2W S13 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby & Wm. Stoffel, crew - March 1963 - C.S. File 53/15-10

 Found - Orig. 6" now 8" Yewwood N.50°E., 9.9 ft., shows good scribing.
 No other orig. BTs. Find stone as recorded.
 Set Brass cap at cor. mkd: County Surveyors Office

	T	32	S	
R2W	S	13	S 18	R1W
	S	24	S 19	

1963

 New BTs- 18" Yewwood bears S.40°E., 18.3 ft. scribed S19 T32S R1W CS BT.
 19" W.Fir bears N.55°W., 82.7 ft. scribed S13 T32 R2W CS BT.
 No trees near to SW.

Glenn S. Baughman - For: U.S. Forest Service - Dec. 1976 - M 56-69

 Found - 1963 DCSO brass cap.
 8" Yew bears N.50°E., 9.9 ft.
 18" Yew bears S.40°E., 18.3 ft.
 20" W.Fir bears N.55°W., 82.7 ft.
 New BT - 6" Fir bears S.75°W., 22.6 ft. "T32S R2W S24 BT"

Survey by Don Bentz - For: U.S. Forest Service - July 19, 1993 C.S. File 63/153-15

 Found - 8" Yew with visible scribing, bears N.50°E., 9.9 ft.
 18" Yew with visible scribing bears S.40°E., 18.3 ft
 (Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec Cor for 13 & 24; 18 & 19, T32-1

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

24" W.Fir with healed blaze bears N.55°W., 82.7 ft.
 12" Fir with healed blaze bears S.75°W., 22.6 ft.
 Found 1" Iron Pipe with Brass Cap lying on the ground, reset per record bearing and distances from existing bearing trees. Reset 1" Iron Pipe with County Surveyor's Office Brass Cap, monument 16" above ground with 24" dia. mound of stone. All bearing trees have a 6" red band painted around the tree and the blazed face painted red. USFS sign 54-3 'Bearing Tree' and sign 54-9 'Land Surveying Monument' are nailed to all bearing trees.

BLM dependent resurvey by Francis J. Simon, Cadastral Surveyor under Group #2007, surveyed April/June. 2002 - (DCSO records Vol. 54 Page(s) 21247-8)

 The cor. of secs. 13, 18, 19, & 24, determined at Douglas County Surveyor rec dists from an orig. BT, 2 county BTs, & a BT mkd. by a private surveyor, from which an original BT
 A yew, 10" dia., bears N.45° E., 9.9 ft., with scribe marks T32S R1W S and other illegible marks visible on partially healed blaze. (Record, N.50°E.)
 and BTs mkd. by the County Surveyor's Office, in 1963
 A yew, 19" dia., bears S.46°E., 18.3 ft., with scribe marks 32S R1W S19 CS BT visible on partially healed blaze.
 A W.Fir, 23" dia., bears N.56°W., 82.7 ft., with a healed blaze.
 and BT mkd. by Baughman
 A fir, 15" dia. bears S.70°W. 22.6 ft with healed blaze
 The 1963 County Surveyor's monument is not recovered and the mound of stone is scattered.

At the corner point
 Set a stainless steel post, 28" long, 2½" dia., 24" in the ground, in a collar of stone, with brass cap mkd.

T 32 S
 R 2 W R 1 W
 S 13 | S 18
 S 24 | S 19
 2002

Deposit a magnet in a white plastic case at the base of the stainless steel post.

John Ransom, USFS - Jonathan Drew - 9/2013 - C.S. 65/85-30

 Found - 3½" BLM brass cap (properly mkd) flush in mound of stone.
 10" Yew (N.45°E.) (9.9 ft) scribe on part. healed double blaze. continued next page

TOWNSHIP 32 RANGE 02 POINT IDENTIFIER # 700400

PRIMARY CORNER DESCRIPTION Sec Cor for 13 & 24; 18 & 19, T32-1

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

19" Yew (S.46°E.) (18.3 ft) scribe on part. healed double blaze
23" W.Fir (N.56°W.) (82.7 ft) healed double blaze
17" Fir (S.70°W.) (22.6 ft) healed double blaze
() = Record per 2002 BLM record
No new accessories added
New nails in BT tags and painted faces & 6" band at head height
Brush cleared around monument and to BTs.
"LAND LINE" flagging tied on monument & guard posts
Corner falls on slight north slope at corner of recent private clear cut, take highway to intersection of closed private logging road on south'ly side of clear cut unit, follow road on foot west-south west to end, then south west to timber corner.
Property line maintained east .5 miles

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - July 11, 2014 - C.S. File 67/41-26

Condition report only

Found - As described in 2002 but:

The 1963 DCSO brass cap/iron pipe monument if found loose on ground surface near 2002 BLM monument. DCSO monument is not practicable to reset, we remove from area to avoid future confusion.

Accessories found as described in 2002

Note - Monument is just inside edge old fir forest which was recently clear-cut in the NE quadrant
Compass decl. 15½°E.