

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 30

Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8535)

 Set a Yew post, 3 ft. long, 4" sq., 24" in the ground for ¼ sec. corner, marked ¼ S on W. face, from which
 A Fir 8" dia., bears N.66°E., 10 lks. mkd. ¼ S BT.
 A Fir 20" dia., bears S.68°W., 64 lks. mkd. ¼ S BT.
 This corner is on the NW. slope of spur, 200 ft. below top.

GLO remonumentation by Hans W. Thielsen, under Group #'s 350 & 422, Surveyed, May/June 1959 - (DCSO records Vol. 30 Page(s) 12800)

 The ¼ sec. cor., determined at record bearing and distance from the remaining original bearing tree:
 A fallen Fir 24" dia., bears S.68°W., 64 lks. marked with a healed blaze.
 At the corner point
 Set an iron post, 28" long, 2 1/2" dia., 20" in the ground, with brass cap mkd:
 ¼
 S 30 | S 29
 T32S R4W
 1959
 from which new bearing trees
 A Fir 22" dia., bears S.88°E., 60 lks. mkd. ¼ S29 BT.
 A Fir 36" dia., bears S.6°W., 90 lks. mkd. ¼ S30 BT.

Survey by Ronald A. Brandt - For: Robert Dollar Co. - July 27, 1970 - C.S. File 55/129-2

 Found - Cadastral brass cap on this corner is intact.
 28" D.Fir N.88°45'E., 39.5 ft., in good condition, now slightly covered with road fill.
 46" D.Fir S.04°W., 59 ft., removed for road construction.
 Scribed -7" D.Fir, N.10°W., 34.9 ft. mkd ¼S T32S R4W RS841 BT

Cor. Fd. and used in BLM resurvey by Roseberry under Group #977, surveyed May/June 1979 (DCSO recs. Vol. 43 Page 16771)

Ron Quimby For: Silver Butte Tbr Co. - July 2019 - M175-78A-B

 Found - Brass cap per CS 55/129-2
 35" Fir bears N.88½°E., 39.5'
 23" Fir bears N.10°W., 34.9'
 New BTs- 15" Fir bears S.25°W., 27.5'
 13" Fir bears N.19°E., 16.8'