

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 & 5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 20 Page(s) 8458)

Set ¼ sec. post from which
 A Fir 20" dia., bears S.75°E., 37 lks. dist.
 A Fir 8" dia., bears S.12°W., 16 lks. dist.

George J. Wenderoth, Deputy Co. Surveyor - Wit: F. Loso - April 1950 - C.S. File 40/246

Drive 1" I.Pipe for corner.
 Scribe - 30" Pine N.2°50'W., 90.9 ft.
 24" Pine N.33°13'E., 69.1 ft.

GLO remonumentation by Hans W. Thielsen, under Group #'s 350 & 422, Surveyed, May/June 1959 - (DCSO records Vol. 30 Page(s) 12801)

The ¼ sec. cor. of secs. 4 and 5, perpetuated with an iron pipe 1" dia., set by the County in 1950, from which bearing trees marked in 1950:

- A Pine 24" dia., bears N.34¼°E., 104 lks. dist., mkd. ¼ S4 BT.
- A Pine 30" dia., bears N.3°W., 151 lks. dist., mkd. ¼ S5 BT.

At the corner point
 Set an iron post, 28 ins. long, 2 1/2 ins. dia., 20 ins. in the ground, with brass cap marked

$\frac{1}{4}$
 S 5 | S 4
 T 32S R4W
 1959

Reset iron pipe alongside iron post.

Fd. OK, B. Shaner, 1963 - RM 1-37

Douglas Co. Surveyors Office - Randall Smith; Stephen J. Flause, crew - Aug. 21, 1985 - C.S. File 62/29-18

Found - 1959 BLM disk on an I.P. protruding 11" above ground, properly marked.
 1" I.P. reset alongside BLM I.P. not found protruding above ground. We did not disturb ground around BLM I.P. to look for 1" I.P.
 30" now a 41" dia., 1½ ft. high Ponderosa Pine stump with partial scribe visible "BT" bears N.1½°W., 91.9 ft. (Rec. N.2°50'W., 90.9 ft.) dist. is to

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 & 5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

face of blaze per Wenderoth) (Rec. N.3°W., 99.7 ft. dist. is in error per 1959 remonumentation of proportioned corner.

24" now a 27" dia. Ponderosa Pine with a well healed double blaze bears N.31½°E., 70.0 ft. (Rec. N.33°13'E., 69.1 ft. dist. is to face of blaze per Wenderoth) (Rec. N.34¼°E., 68.6 ft. dist. is to edge of bark per 1959 remonumentation of proportioned corner.

New BTs -11" dia. I.Cedar double blaze and scribed ¼ S5 CS BT, bears S.52°W., 6.8 ft.

7" dia., D.Fir double blazed and scribed ¼ S5 CS BT, bears N.60°W., 65.2 ft.

9" dia. P.Pine double blazed and scribed ¼ S4 CS BT" bears S.62½°E., 47.7 ft.

Corner lies in a N-S fence line.

Found OK by G. Lang, Feb. 2000 - M135-61
 Fd. BLM BC & BTs by Troy Rambo, July 2002 M140-74

BLM dependent resurvey by Kevin G Mulder, Cadastral Surveyor, under Group No. 2627; Surveyed April/May 2013 - (DCSO records Vol. 58 Page(s) 23059)

The ¼ sec. cor. of secs. 4 and 5, perpetuated by the Douglas County Surveyor's Office in 1985, monumented with an iron post, 2½" dia., firmly set, projecting 12" above the ground, with brass cap (properly) mkd.

from which the remains of BTs mkd. by Wenderoth, in 1950

A pine, 32" dia., bears N.31½°E., 69.9 ft., with a healed double blaze. (Record, N.34¼°E., 68.6 ft.)

A rotted pine stump, size indeterminate, bears N.4¼°W., 91.9 ft., no marks visible. (Record, N.3°W., 99.7 ft.)

and BTs mkd. by the Douglas County Surveyor's Office in 1985

A ponderosa pine, 17" dia., bears S.62¾°E., 47.8 ft., with a healed double blaze.

A cedar, 17" dia., bears S.52°W., 7.0 ft., with a healed double blaze.

A fir, 14" dia., bears N.60°W., 64.9 ft., with a healed double blaze.

An iron pipe, 1 in. diam., is alongside the iron post.

Fd. ok by R. Brown 1/2015 - M166-31

