

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19, 20, 29 and 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - GLO survey by Wells Lake, Deputy Surveyor, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8573)

Set post cor. to secs.19, 20, 29 and 30, from which
A W.Thorn 8" dia., bears N.36°W., 23 lks.
An Ash 10" dia., bears S.50°W., 24 lks.
A V.Maple 7" dia., bears S.12°E., 16 lks.
A W.Ash 12" dia., bears N.71°E., 15 lks.

George J. Wenderoth, D.C.S. - Wit: L. Pureblood - August 1950
M 32-2; M 27-12; C.S. File 40/247; C.S. File 40/268

Orig. corner washed away.
Set from ¼ corners W - N and S.
Drive ½" I.Pipe.
Scribe - 20" Alder N.57°20'W., 28.5 ft.
14" Ash N.73°20'E., 57.3 ft.
14" Alder S.52°15'W., 59.5 ft.
8" Alder S.71°10'E., 19.2 ft.

BLM dependent resurvey by Joseph S. Gawron and Norman J. McDonald, under Group #472, surveyed June/July 1962 (DCSO records Vol. 32 Page(s) 13254)

Point for the sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 30 ins. long, 2 1/2 ins. dia., 26 ins. in the ground, with brass cap marked
T 32 S R 5 W
S 19 | S 20
S 30 | S 29
1962

from which
An Ash 22" dia., bears N.30°E., 22 lks. dist., mkd. T32S R5W S20 BT.
An Ash 9" dia., bears S.48½°E., 34 lks. dist., mkd. T32S R5W S29 BT.
An Ash 18" dia., bears N.68½°W., 65 lks. dist., mkd. T32S R5W S19 BT.

From this point, an iron pipe 1½" dia., firmly set, protruding 14" above ground, bears S.22°W., 0.135 chs. distance.
from which locally established bearing trees
An Alder 14" dia., bears S.71¼°E., 29 lks. dist., with a partially healed blaze.

(Cont. Next Page)

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 200300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19, 20, 29 and 30

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

An Alder 20" dia., bears S.52¼°W., 90 lks. dist., with a partially healed blaze.
An Alder 24" dia., bears N.57¼°W., 43 lks. dist., with a partially healed blaze.

NOTE: See M 99-33 - reports corner and accessories destroyed by creek.

Per Ray Wytcherly, July 2005 - M146-24
Section corner falls in water. Corner & BTs destroyed.