

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5, 6, 7 and 8

| Alias | Description |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |

GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #729, dated Dec. 24, 1900 and special instructions dated Sept. 12, 1901 (DCSO records Vol. 20 Page(s) 8607)

-----  
 Set a Yew post, 3 ft. long, 4" sq., 24" in the ground, for cor. of secs. 5, 6, 7 and 8, marked T32S S5 on NE.; R5W S8 on SE.; S7 on SW.; and S6 on NW. faces, with 5 notches on S. and E. edges, from which

- A Fir 36" dia., bears N.71°E., 33 lks. mkd. T32S R5W S5 BT
- A W.Fir 12" dia., bears S.42°E., 21 lks. mkd. T32S R5W S8 BT
- A Fir 30" dia., bears S.20°W., 60 lks. mkd. T32S R5W S7 BT
- A Fir 28" dia., bears N.41½°W., 32 lks. mkd. T32S R5W S6 BT

BLM dependent resurvey by Joseph S. Gawron and Norman J. McDonald, under Group #472, surveyed June/July 1962 (DCSO records Vol. 32 Page(s) 13257-58)

-----  
 The Sec. cor., determined from the remains of the original bearing trees:

- A sawed Fir stump 40" dia., bears N.71°E., 33 lks. dist., with a rotted face.
- A Fir snag 40" dia., bears S.20°W., 60 lks. dist., with a burned face.
- A Fir snag 38" dia., bears N.41½°W., 32 lks. dist., mkd. T32S R5W S6 on exposed face of burned face.

At the corner point

Set an iron post, 30 ins. long, 2 1/2 ins. dia., 28 ins. in the ground, with brass cap marked

T 32 S R 5 W  
 S 6 | S 5  
 S 7 | S 8  
 1962

from which

- A Chinquapin 6" dia., bears N.65°E., 35 lks., mkd. T32S R5W S5 BT.
- A Cedar 6" dia., bears S.9°E., 55 lks. mkd. T32S R5W S8 BT
- A Cedar 6" dia. bears S.14°W., 96 lks. mkd. T32S R5W S7 BT
- A Fir 6" dia., bears N.65°W., 45 lks., mkd. T32S R5W S6 BT

James McIntosh, Oregon Dept. of Forestry - 3/2006 - M150-23

Found - BLM P/C, 1962 (in place)

- 36" fir (1901) N.71°E., 33 lks (now 32"x2' high rotted stump in place, face rotted, BLM BTT)
- 12" W.Fir (1901) S.42°E., 21 lks., (missing)
- 30" Fir (1901) S.20°W., 60 lks (now 38"x3½' high rotted stump in place, face rotted, BLM BTT)

continued next page

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 200600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5, 6, 7 and 8

|       |       |             |       |
|-------|-------|-------------|-------|
| Alias | _____ | Description | _____ |
| Alias | _____ | Description | _____ |
| Alias | _____ | Description | _____ |
| Alias | _____ | Description | _____ |

|       |  |
|-------|--|
|       | 28" fir (1901) N.41½°W., 32 lks (now 35"x8' high rotted stub in place, face rotted, BLM BTT) |
|       | 6" chinquapin N.65°E., 35 lks (missing)  |
|       | 6" cedar S.9°E., 55 lks (missing)  |
|       | 6" cedar S.14°W., 96 lks (now 20" in place, face closed, BLM BTT)                            |
|       | 6" fir N.65°W., 45 lks (now 22" in place, face closed, BLM BTT)                              |
| New - | 21" fir S.55°E., 27.1' to aluminum nail in BT face scribed (T32SR5WS8BT) BTT                 |
|       | 17" fir N.32°E., 4.6' to aluminum nail in BT face scribed (T32SR5WS5BT) BTT                  |
|       |  |