

PRIMARY CORNER DESCRIPTION West WP to 1/4 Cor. Secs. 2 & 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Resurvey, by Francis J. Simon, Cadastral Surveyor, under Group No. 1733. Surveyed May thru Nov. 1994. (D.C.S.O. records Vol. 52 Page(s) 19683-84)

At the point for the 1/4 sec. cor. of secs. 2 and 11, determined by the irregular boundary method. This point falls in the southbound lanes of Interstate Highway No. 5, and is unsuitable for monumentation. There is no evidence of the 1955 remonumentation of the original corner.

At 4.55 chains west of the 1/4 corner: Point for a witness point on line bet. secs. 2 and 11.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 23 ins. in the ground, with brass cap mkd.

WP
S 2
S 11
1994

from which

A fir, 6" dia., bears S.59°E., 50½ lks., mkd. X BT.

A fir, 6" dia., bears N.36°W., 39 lks., mkd. X BT.

Witness point is located in a woven wire fence with three strands of barbed wire on top, bears N.45°W. and S.45°E.

Fd. OK by M. Heimbürger, Oct. 1999 - CS file 65/25-11

Fd. Ok by M. Heimbürger, May 2005 - M148-24

BLM Dependent resurvey by Arthur R. Rambo, & Francis Simon Cadastral Surveyors under Group No. 2143, surveyed May 2006/Feb. 2007 - (DCSO records, Vol. 55 Page(s) 21695)

Point for the ¼ sec. cor. of secs. 2 and 11, determined at record bearing and distance from the 1994 witness points. Point falls in the southbound lane of Interstate Highway No. 5. No permanent monument set.

From this point, the witness point in the westerly direction, bears N.89°39'00"W., 300.30 ft., monumented with a stainless steel post, 2½" dia., firmly set, projecting 5" above the ground, with brass cap mkd. WP S2 S11 1994 and a horizontal line, from which bearing trees mkd. by Simon in 1994:

A fir, 6" dia., bears S.59°E., 33.3 ft., with a healed double blaze.

A fir, 7" dia., bears N.36°W., 25.7 ft., with a healed double blaze.