

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 540600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 11

| Alias | Description |
|-------|-------------|
| _____ | _____ |
| Alias | Description |
| _____ | _____ |
| Alias | Description |
| _____ | _____ |
| Alias | Description |
| _____ | _____ |

Original - GLO survey by Wells Lake, Deputy Surveyor, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8566)

Set ¼ sec. post, from which
 A Cherry 4" dia., bears S.41°W., 42 lks.
 A Cherry 5" dia., bears N.66°W., 50 lks.

George J. Wenderoth - August 1952 - C.S. File 45/98

Set Axle shaft.
 14" Cedar S.43°15'W., 44.6 ft.
 20" Fir S.2°20'E., 39.2 ft.

GLO resurvey by Hans W. Thielsen, under Group #320, Surveyed, Oct./Nov. 1955 - (DCSO records Vol. 28 Page(s) 11795-96)

The ¼ sec. cor., perpetuated by an axle shaft, 1½" dia., 10" above ground, set by the County Surveyor in 1951.
from which bearing trees marked by the County:
 A Fir 20" dia., bears S.2¼°E., 59 lks., marked ¼ S CS BT.
 A Cedar 14" dia., bears S.43°W., 62 lks., marked ¼ S CS BT
At the corner point
Set an iron post, 36" long, 1" dia., 30" in the ground, with brass cap marked: ¼ S2/S11 1955
from which new bearing trees:
 An Alder 12" dia., bears N.19°E., 18 lks. marked ¼ S 2 BT.
 A W.Fir 18" dia., bears S.1½°W., 91 lks. marked ¼ S 11 BT.

Searched for, Not found, DCSO, Aug. 1967

BLM Resurvey, by Francis J. Simon, Cadastral Surveyor, under Group No. 1733. Surveyed May/Nov. 1994. (DCSO records Vol. 52 Pages 19683-84)

At the point for the 1/4 sec. cor. of secs. 2 and 11, determined by the irregular boundary method. This point falls in the southbound lanes of Interstate Highway No. 5, and is unsuitable for monumentation. There is no evidence of the 1955 remonumentation of the original corner.
See PLSS # 535600 for the W.P. 4.55 chs West, & see PLSS # 546600 for the W.P. 6.30 chs East of the ¼ corner.