

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION S C for Secs. 32 and 33 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 20 Page(s) 8704) (and pages 8742-43)

Set a Chinquapin post, for S C to Secs. 32 and 33 viz., 4½ ft. long, 4" sq., 20" in the ground, mkd. S C T32S R7W on N.; S33 on E.; and S32 on W., from which
A Pine 24" dia., bears N.38°E., 35 lks. dist., mkd. S C T32S R7W S33 BT.
A Fir 34" dia., bears N.45°W., 53 lks. dist., mkd. S C T32SR7W S32 BT.
A Fir 14" dia., bears S.58°W., 19 lks. dist., mkd. S C T33S R7W S5 BT.

GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #729, dated Dec. 24, 1900 and special instructions dated Sept. 12, 1901 (DCSO records Vol. 21 Page(s) 9052)

The cor. of secs. 32 and 33, which having disappeared, I re-establish it, by setting a granite stone, 15 x 8 x 6 ins., 10" in the ground, for standard corner of secs. 32 and 33, marked S C on N.; with 4 grooves on E. and 2 notches on W. faces, and witnessed as described by the surveyors general.

Survey by Norman D. Price - For: Dollar and Patterson Lumber Co. - March/Aug. 1954 - C.S. File 41/301

Determined at the record bearing and distance from the original SW BT; all other evidence of the original corner monument has disappeared.
Set an iron post 3 ft. long, 2" dia., 28" in the ground, mkd. RS33, from which the only original bearing tree
A D.Fir 20" dia., bears S.58°W., 19 lks. dist., mkd. on bark T33S R7W S5 SC BT.
And a new bearing tree
A D.Fir 14" dia., bears N.41½°E., 46 lks. dist., mkd. T32S R7W S33 SC RS33 BT.

Searched for, not found, Area heavily logged. DCSO, J. Powell, Dec. 13, 1967 (C.S. File 54/36-116)

March 21, 1968 - **32|33 which was looked for and not fd is found and OK DCSO** JP C.S. 54/36-118 (added 10/12/2016)

Found OK By R. Templin, July 1995 - M122-53

(Cont. Next Page)

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION SC for secs. 32 & 33 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Do. Co. Surveyors Office - Randall Smith & Stephen Flause -
10/2/95 - C.S. 64/64-7

Found - 2" O.D. Iron pipe protrudes 6" above ground.
1900 corner stone set by Theil not Fd.
14" now down and rotted D.Fir, no scribing visible,
root hole bears S.58°W., 12.5'.
14" now 18" dia. 2' high D.Fir stump, with a fully
healed single blaze, bears N.41½°E. 30.4'.
Found a root hole near original brg. & dist. of NE
OBT (N38°E., 23.1')
Set- 1954 price 2" dia. iron pipe is firmly set in
ground, did not want to disturb ground to set a
BC/IP as it would not be stable.
New BTs- 9" dia. D.Fir, double blazed and scribed "T32S R7W
SC 32 CS BT", bears N.10°W., 27.8'.
3" dia. tan oak, double blazed and scribed "X BT",
bears S.89°E., 5.2'.
4" dia. Pistol butt Chinquapin, double blazed and
scribed "X BT", center of root crown bears
S.50°W., 25.7'.
Corner is on a steep north slope approx. 50' south of a
gravel road.

Ron Quimby - Crew: N. Fromdahl & D. Manring - 9/2014 - C.S.
File 65/86-19

Condition report only
Found - 2" O.D. iron pipe.
18" D.Fir stump N.41½°E., 30.4 ft.
16" D.fir N.10°W., 27.8 ft. healed scar.
5" T.Oak S.89°E., 5.2 ft.
6" chinquapin S.50°W., 25.7 ft.
Note - Area badly burnt 2013. Corner on North slope approx.
50' south of road.
Compass decl. 15½°E.