

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 21 Page(s) 8741)

Marked a Fir tree 8" dia., for the 1/4 sec. cor. mkd. 1/4 S on N. side, from which

A Fir 16" dia., bears N.60°E., 9 lks. dist., mkd. 1/4 S BT.

A Fir 10" dia., bears S.10°E., 25 lks. dist., mkd. 1/4 S BT

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #543, surveyed June, 1964 (DCSO records Vol. 33 Page(s) 13652)

The 1/4 sec. cor., monumented with the remains of the original corner tree, a rotted Fir stump, 18" dia., mkd. 1/4 S in negative on piece of overgrowth lying alongside the stump, from which the remains of the original bearing trees:

A rotted Fir stump 30" dia., bears N.76°E., 9 lks. dist., with no marks remaining. (Rec. N.60°E.)

A Fir snag 14" dia., bears S.7 1/4°W., 25 lks. dist., with a healed blaze. (Rec. S.10°E.)

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 22 ins. in the ground, in the center of the rotted stump, with brass cap marked T 32 S R 7 W

1/4 $\frac{S \quad 3}{S \quad 10}$
1964

from which new bearing trees:

A Fir 8" dia., bears N.82 1/4°E., 48 lks. dist., mkd. 1/4 S3 BT

A Fir 8" dia., bears S.24 3/4°W., 43 lks. dist., mkd. 1/4 S10 BT.